

This document does not apply to HPE Superdome servers. For information on HPE Superdome, see the following links:

[HPE Integrity Superdome X](#)

[HPE Superdome Flex](#)

Information on HPE Synergy supported VMware ESXi OS releases, HPE ESXi Custom Images and HPE Synergy Custom SPPs is available at:

[VMware OS Support Tool for HPE Synergy](#)

Information on HPE Synergy Software Releases is available at:

[HPE Synergy Software Releases - Overview](#)

Gen10 SPP v2023.03.00.00 Release Notes for VMware ESXi 7.0

[BIOS \(Login Required\) - System ROM](#)

[Driver - Lights-Out Management](#)

[Driver - Network](#)

[Driver - Storage Controller](#)

[Firmware - Network](#)

[Firmware - NVDIMM](#)

[Firmware - Storage Controller](#)

[Firmware - Storage Fibre Channel](#)

[Software - Management](#)

[Software - Storage Controller](#)

[Software - Storage Fibre Channel](#)

[Software - System Management](#)

BIOS (Login Required) - System ROM

[Top](#)

ROM Flash Firmware Package - HPE Apollo 2000 Gen10/HPE ProLiant XL170r/XL190r Gen10 (U38) Servers

Version: 2.76_02-09-2023 (**Recommended**)

Filename: U38_2.76_02_09_2023.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE ProLiant XL170/XL190 Gen10 System ROM - U38

Release Version:

2.76_02-09-2023

Last Recommended or Critical Revision:

2.76_02-09-2023

Previous Revision:

2.72_09-29-2022

Firmware Dependencies:

None

Enhancements/New Features:

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Enhancements

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

ROM Flash Firmware Package - HPE Apollo 4200 Gen10/HPE ProLiant XL420 Gen10 (U39) Servers
Version: 2.76_02-09-2023 (**Recommended**)
Filename: U39_2.76_02_09_2023.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE Apollo 4200 Gen10/ProLiant XL420 Gen10 System ROM - U39

Release Version:

2.76_02-09-2023

Last Recommended or Critical Revision:

2.76_02-09-2023

Previous Revision:

2.72_09-29-2022

Firmware Dependencies:

None

Enhancements/New Features:

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Enhancements

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

ROM Flash Firmware Package - HPE Apollo 4510 Gen10/HPE ProLiant XL450 Gen10 (U40) Servers
Version: 2.76_02-09-2023 (**Recommended**)
Filename: U40_2.76_02_09_2023.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE Apollo 4510 Gen10/HPE ProLiant XL450 Gen10 System ROM - U40

Release Version:

2.76_02-09-2023

Last Recommended or Critical Revision:

2.76_02-09-2023

Previous Revision:

2.72_09-29-2022

Firmware Dependencies:

None

Enhancements/New Features:

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Fixes**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Enhancements

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

ROM Flash Firmware Package - HPE Apollo 6500 Gen10/HPE ProLiant XL270d Gen10 (U45) Servers

Version: 2.76_02-09-2023 (**Recommended**)

Filename: U45_2.76_02_09_2023.fwpkg

Important Note!**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE ProLiant XL270d Gen10 System ROM - U45

Release Version:

2.76_02-09-2023

Last Recommended or Critical Revision:

2.76_02-09-2023

Previous Revision:

2.72_09-29-2022

Firmware Dependencies:

None

Enhancements/New Features:

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Enhancements

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE ProLiant DL110 Gen10 Plus System ROM - U56

Release Version:

1.72_02-02-2023

Last Recommended or Critical Revision:

1.72_02-02-2023

Previous Revision:

1.68_10-27-2022

Firmware Dependencies:

None

Enhancements/New Features:

Added "Important: Intel(R) NVMe and Intel(R) VROC are not supported when the Boot Mode is configured in Legacy BIOS Mode." message into the RBSU help description for Intel NVMe VROC option.

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when Workload Profile sets to Custom and Power Regulator sets to OS Control Mode.

Downgraded several debug messages from DEBUG_ERROR to DEBUG_INFO level. Removed unnecessary error messages in BIOS serial log.

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-21216, CVE-2022-32231, CVE-2022-26343, CVE-2022-33196, CVE-2022-38090 and CVE-2022-33972. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1s update which provides mitigation for security vulnerabilities documented as CVE-2022-2097.

Addressed an issue where the controller name was not displayed in Japanese when MegaRAID was switched to Japanese, .

Addressed an issue where NVMe drive info was not displayed properly in iLO when Intel PCH VMD is enabled in RBSU.

Addressed an issue where Intel VROC SATA firmware shows N/A under PCI Device information.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-21216, CVE-2022-32231, CVE-2022-26343, CVE-2022-33196, CVE-2022-38090 and CVE-2022-33972. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1s update which provides mitigation for security vulnerabilities documented as CVE-2022-2097.

Addressed an issue where the controller name was not displayed in Japanese when MegaRAID was switched to Japanese, .

Addressed an issue where NVMe drive info was not displayed properly in iLO when Intel PCH VMD is enabled in RBSU.

Addressed an issue where Intel VROC SATA firmware shows N/A under PCI Device information.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Known Issues:

None

Enhancements

Added "Important: Intel(R) NVMe and Intel(R) VROC are not supported when the Boot Mode is configured in Legacy BIOS Mode." message into the RBSU help description for Intel NVMe VROC option.

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when Workload Profile sets to Custom and Power Regulator sets to OS Control Mode.

Downgraded several debug messages from DEBUG_ERROR to DEBUG_INFO level. Removed unnecessary error messages in BIOS serial log.

ROM Flash Firmware Package - HPE ProLiant DL160 Gen10/DL180 Gen10 (U31) Servers

Version: 2.76_02-09-2023 **(Recommended)**

Filename: U31_2.76_02_09_2023.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE ProLiant DL160 Gen10/DL180 Gen10 System ROM - U31

Release Version:

2.76_02-09-2023

Last Recommended or Critical Revision:

2.76_02-09-2023

Previous Revision:

2.72_09-29-2022

Firmware Dependencies:

None

Enhancements/New Features:

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security

vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Enhancements

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

ROM Flash Firmware Package - HPE ProLiant DL20 Gen10 (U43) Servers

Version: 2.68_01-12-2023 **(Recommended)**

Filename: U43_2.68_01_12_2023.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE ProLiant DL20 Gen10 System ROM - U43

Release Version:

2.68_01-12-2023

Last Recommended or Critical Revision:

2.68_01-12-2023

Previous Revision:

2.64_10-13-2022

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-33894 and CVE-2022-26837. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for security vulnerabilities documented as CVE-2022-37434.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUN. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture defaults.

Addressed an issue where some Chinese and Japaneses translations were missing from RBSU.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-33894 and CVE-2022-26837. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for security vulnerabilities documented as CVE-2022-37434.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUN. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture defaults.

Addressed an issue where some Chinese and Japaneses translations were missing from RBSU.

Known Issues:

None

ROM Flash Firmware Package - HPE ProLiant DL20 Gen10 Plus Servers
Version: 1.68_01-12-2023 **(Recommended)**
Filename: U60_1.68_01_12_2023.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE ProLiant DL20 Gen10 Plus System ROM - U60

Release Version:

1.68_01-12-2023

Last Recommended or Critical Revision:

1.68_01-12-2023

Previous Revision:

1.64_10-20-2022

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-26837, CVE-2022-38090 and CVE-2022-30704. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for security vulnerabilities documented as CVE-2022-37434.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1s update which provides mitigation for security vulnerabilities documented as CVE-2022-2097.

Addressed an issue where RBSU PCI device information page does not display the Intel VROC SATA firmware version correctly.

Addressed an issue where NVMe drive info cannot display properly in iLO web when PCH VMD is enabled.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Known Issues:

None

Fixes**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-26837, CVE-2022-38090 and CVE-2022-30704. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for security vulnerabilities documented as CVE-2022-37434.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1s update which provides mitigation for security vulnerabilities documented as CVE-2022-2097.

Addressed an issue where RBSU PCI device information page does not display the Intel VROC SATA firmware version correctly.

Addressed an issue where NVMe drive info cannot display properly in iLO web when PCH VMD is enabled.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Known Issues:

None

Important Note!

Important Notes:

None

Deliverable Name:

HPE ProLiant DL325 Gen10 System ROM - A41

Release Version:

2.68_02-02-2023

Last Recommended or Critical Revision:

2.68_02-02-2023

Previous Revision:

2.64_11-17-2022

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

This revision of the System ROM updates zlib to 1.2.13 which provides mitigation for BIOS security vulnerability documented as CVE-2022-37434.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-37434>). This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

Addressed an issue where some Chinese translation is missing from RBSU.

Known Issues:

None

Fixes**Important Notes:**

None

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM updates zlib to 1.2.13 which provides mitigation for BIOS security vulnerability documented as CVE-2022-37434.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-37434>). This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

Addressed an issue where some Chinese translation is missing from RBSU.

Known Issues:

None

ROM Flash Firmware Package - HPE ProLiant DL360 Gen10 (U32) Servers

Version: 2.76_02-09-2023 **(Recommended)**

Filename: U32_2.76_02_09_2023.fwpkg

Important Note!**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE ProLiant DL360 Gen10 System ROM - U32

Release Version:

2.76_02-09-2023

Last Recommended or Critical Revision:

2.76_02-09-2023

Previous Revision:

2.72_09-29-2022

Firmware Dependencies:

None

Enhancements/New Features:

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Fixes**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Enhancements

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE DL380 Gen10 System ROM - U30

Release Version:

2.76_02-09-2023

Last Recommended or Critical Revision:

2.76_02-09-2023

Previous Revision:

2.72_09-29-2022

Firmware Dependencies:

None

Enhancements/New Features:

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Enhancements

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

ROM Flash Firmware Package - HPE ProLiant DL385 Gen10 (A40) Servers

Version: 2.68_02-02-2023 (**Recommended**)

Filename: A40_2.68_02_02_2023.fwpkg

Important Note!

Important Notes:

None

Deliverable Name:

HPE DL385 Gen10 System ROM - A40

Release Version:

2.68_02-02-2023

Last Recommended or Critical Revision:

2.68_02-02-2023

Previous Revision:

2.64_11-17-2022

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

This revision of the System ROM updates zlib to 1.2.13 which provides mitigation for BIOS security vulnerability documented as CVE-2022-37434.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-37434>). This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

Addressed an issue where some Chinese translation is missing from RBSU.

Known Issues:

None

Fixes

Important Notes:

None

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM updates zlib to 1.2.13 which provides mitigation for BIOS security vulnerability documented as CVE-2022-37434.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-37434>). This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

Addressed an issue where some Chinese translation is missing from RBSU.

Known Issues:

None

ROM Flash Firmware Package - HPE ProLiant DL560 Gen10/DL580 Gen10 (U34) Servers
Version: 2.76_02-09-2023 (**Recommended**)
Filename: U34_2.76_02_09_2023.fwpkg

Important Note!**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE ProLiant DL560 Gen10/DL580 Gen10 System ROM - U34

Release Version:

2.76_02-09-2023

Last Recommended or Critical Revision:

2.76_02-09-2023

Previous Revision:

2.72_09-29-2022

Firmware Dependencies:

None

Enhancements/New Features:

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Fixes**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Enhancements

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

ROM Flash Firmware Package - HPE ProLiant MicroServer Gen10 Plus (U48) Servers

Version: 2.68_01-12-2023 (**Recommended**)

Filename: U48_2.68_01_12_2023.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE MicroServer Gen10 Plus System ROM - U48

Release Version:

2.68_01-12-2023

Last Recommended or Critical Revision:

2.68_01-12-2023

Previous Revision:

2.64_10-13-2022

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-33894 and CVE-2022-26837. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for security vulnerabilities documented as CVE-2022-37434.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUN. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture defaults.

Addressed an issue where some Chinese and Japanese translations were missing from RBSU.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-33894 and CVE-2022-26837. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for security vulnerabilities documented as CVE-2022-37434.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUN. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture defaults.

Addressed an issue where some Chinese and Japaneses translations were missing from RBSU.

Known Issues:

None

ROM Flash Firmware Package - HPE ProLiant MicroServer Gen10 Plus v2 (U64) Servers
Version: 1.68_01-12-2023 (**Recommended**)
Filename: U64_1.68_01_12_2023.fwpkg

Important Note!**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE ProLiant MicroServer Gen10 Plus v2 System ROM - U64

Release Version:

1.68_01-12-2023

Last Recommended or Critical Revision:

1.68_01-12-2023

Previous Revision:

1.64_10-20-2022

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-26837, CVE-2022-38090 and CVE-2022-30704. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for security vulnerabilities documented as CVE-2022-37434.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1s update which provides mitigation for security vulnerabilities documented as CVE-2022-2097.

Addressed an issue where RBSU PCI device information page does not display the Intel VROC SATA firmware version correctly.

Addressed an issue where NVMe drive info cannot display properly in iLO web when PCH VMD is enabled.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Known Issues:

None

Fixes**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-26837, CVE-2022-38090 and CVE-2022-30704. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for security vulnerabilities documented as CVE-2022-37434.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1s update which provides mitigation for security vulnerabilities documented as CVE-2022-2097.

Addressed an issue where RBSU PCI device information page does not display the Intel VROC SATA firmware version correctly.

Addressed an issue where NVMe drive info cannot display properly in iLO web when PCH VMD is enabled.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Known Issues:

None

ROM Flash Firmware Package - HPE ProLiant ML110 Gen10 (U33) Servers
Version: 2.76_02-09-2023 **(Recommended)**
Filename: U33_2.76_02_09_2023.fwpkg

Important Note!**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE ProLiant ML110 Gen10 System ROM - U33

Release Version:

2.76_02-09-2023

Last Recommended or Critical Revision:

2.76_02-09-2023

Previous Revision:

2.72_09-29-2022

Firmware Dependencies:

None

Enhancements/New Features:

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Enhancements

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

ROM Flash Firmware Package - HPE ProLiant ML30 Gen10 (U44) Servers

Version: 2.68_01-12-2023 **(Recommended)**

Filename: U44_2.68_01_12_2023.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE ProLiant ML30 Gen10 System ROM - U44

Release Version:

2.68_01-12-2023

Last Recommended or Critical Revision:

2.68_01-12-2023

Previous Revision:

2.64_10-13-2022

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-33894 and CVE-2022-26837. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for security vulnerabilities documented as CVE-2022-37434.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUN. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture defaults.

Addressed an issue where some Chinese and Japaneses translations were missing from RBSU.

Known Issues:

None

Fixes**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-33894 and CVE-2022-26837. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for security vulnerabilities documented as CVE-2022-37434.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUN. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture defaults.

Addressed an issue where some Chinese and Japaneses translations were missing from RBSU.

Known Issues:

None

ROM Flash Firmware Package - HPE ProLiant ML30 Gen10 Plus Servers
Version: 1.68_01-12-2023 **(Recommended)**
Filename: U61_1.68_01_12_2023.fwpkg

Important Note!**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE ProLiant ML30 Gen10 Plus System ROM - U61

Release Version:

1.68_01-12-2023

Last Recommended or Critical Revision:

1.68_01-12-2023

Previous Revision:

1.64_10-20-2022

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-26837, CVE-2022-38090 and CVE-2022-30704. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for security vulnerabilities documented as CVE-2022-37434.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1s update which provides mitigation for security vulnerabilities documented as CVE-2022-2097.

Addressed an issue where RBSU PCI device information page does not display the Intel VROC SATA firmware version correctly.

Addressed an issue where NVMe drive info cannot display properly in iLO web when PCH VMD is enabled.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-26837, CVE-2022-38090 and CVE-2022-30704. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for security vulnerabilities documented as CVE-2022-37434.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1s update which provides mitigation for security vulnerabilities documented as CVE-2022-2097.

Addressed an issue where RBSU PCI device information page does not display the Intel VROC SATA firmware version correctly.

Addressed an issue where NVMe drive info cannot display properly in iLO web when PCH VMD is enabled.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Known Issues:

None

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE ProLiant ML350 Gen10 System ROM - U41

Release Version:

2.76_02-09-2023

Last Recommended or Critical Revision:

2.76_02-09-2023

Previous Revision:

2.72_09-29-2022

Firmware Dependencies:

None

Enhancements/New Features:

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Enhancements

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

ROM Flash Firmware Package - HPE ProLiant XL220n/XL290n Gen10 Plus 1U Node and 2U Node Configure-to-order Server (U47)
Version: 1.72_02-02-2023 (**Recommended**)
Filename: U47_1.72_02_02_2023.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE ProLiant XL220n Gen10 Plus 1U/XL290n Gen10 Plus 2U Node CTO Server System ROM - U47

Release Version:

1.72_02-02-2023

Last Recommended or Critical Revision:

1.72_02-02-2023

Previous Revision:

1.68_10-27-2022

Firmware Dependencies:

None

Enhancements/New Features:

Added "Important: Intel(R) NVMe and Intel(R) VROC are not supported when the Boot Mode is configured in Legacy BIOS Mode." message into the RBSU help description for Intel NVMe VROC option.

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when Workload Profile sets to Custom and Power Regulator sets to OS Control Mode.

Downgraded several debug messages from DEBUG_ERROR to DEBUG_INFO level. Removed unnecessary error messages in BIOS serial log.

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-21216, CVE-2022-32231, CVE-2022-26343, CVE-2022-33196, CVE-2022-38090 and CVE-2022-33972. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1s update which provides mitigation for security vulnerabilities documented as CVE-2022-2097.

Addressed an issue where the controller name was not displayed in Japanese when MegaRAID was switched to Japanese, .

Addressed an issue where NVMe drive info was not displayed properly in iLO when Intel PCH VMD is enabled in RBSU.

Addressed an issue where Intel VROC SATA firmware shows N/A under PCI Device information.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-21216, CVE-2022-32231, CVE-2022-26343, CVE-2022-33196, CVE-2022-38090 and CVE-2022-33972. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1s update which provides mitigation for security vulnerabilities documented as CVE-2022-2097.

Addressed an issue where the controller name was not displayed in Japanese when MegaRAID was switched to Japanese, .

Addressed an issue where NVMe drive info was not displayed properly in iLO when Intel PCH VMD is enabled in RBSU.

Addressed an issue where Intel VROC SATA firmware shows N/A under PCI Device information.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Known Issues:

None

Enhancements

Added "Important: Intel(R) NVMe and Intel(R) VROC are not supported when the Boot Mode is configured in Legacy BIOS Mode." message into the RBSU help description for Intel NVMe VROC option.

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when Workload Profile sets to Custom and Power Regulator sets to OS Control Mode.

Downgraded several debug messages from DEBUG_ERROR to DEBUG_INFO level. Removed unnecessary error messages in BIOS serial log.

ROM Flash Firmware Package - HPE ProLiant XL225n Gen10 Plus (A46) Servers

Version: 2.68_02-06-2023 **(Recommended)**

Filename: A46_2.68_02_06_2023.fwpkg

Important Note!

Important Notes:

None

Deliverable Name:

HPE ProLiant XL225n Gen10 Plus System ROM - A46

Release Version:

2.68_02-06-2023

Last Recommended or Critical Revision:

2.68_02-06-2023

Previous Revision:

2.64_11-30-2022

Firmware Dependencies:

None

Enhancements/New Features:

Add new System Configuration (RBSU) configuration options that allow controlling the processors P0 (maximum) frequency. This includes the Custom Pstate0 option with settings of Auto (default) and Manual and the Pstate0 Frequency(MHz) option that allows

setting the P0 frequency. When the Custom Pstate0 option is configured for Manual, the value of the Pstate0 Frequency(MHz) is used for the processors P0 frequency. When the Custom Pstate0 option is configured for Auto, the processor uses its normal, maximum P0 frequency and the Pstate0 Frequency(MHz) option is not configurable. In System Configuration (RBSU), these options are located under the BIOS/Processor Options. This setting has the following Redfish properties:

/redfish/v1/systems/1/bios/settings/CustomPstate0

/redfish/v1/systems/1/bios/settings/Pstate0Frequency

Problems Fixed:

This revision of the System ROM updates zlib to 1.2.13 which provides mitigation for BIOS security vulnerability documented as CVE-2022-37434.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-37434>). This security vulnerability is documented in the CVE report site.

This revision of the System ROM includes the v1.1.1s openssl which provides mitigation for BIOS security vulnerability documented as CVE-2022-2097.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-2097>). This security vulnerability is documented in the CVE report site.

Known Issues:

None

Fixes

Important Notes:

None

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM updates zlib to 1.2.13 which provides mitigation for BIOS security vulnerability documented as CVE-2022-37434.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-37434>). This security vulnerability is documented in the CVE report site.

This revision of the System ROM includes the v1.1.1s openssl which provides mitigation for BIOS security vulnerability documented as CVE-2022-2097.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-2097>). This security vulnerability is documented in the CVE report site.

Known Issues:

None

Enhancements

Add new System Configuration (RBSU) configuration options that allow controlling the processors P0 (maximum) frequency. This includes the Custom Pstate0 option with settings of Auto (default) and Manual and the Pstate0 Frequency(MHz) option that allows setting the P0 frequency. When the Custom Pstate0 option is configured for Manual, the value of the Pstate0 Frequency(MHz) is used for the processors P0 frequency. When the Custom Pstate0 option is configured for Auto, the processor uses its normal, maximum P0 frequency and the Pstate0 Frequency(MHz) option is not configurable. In System Configuration (RBSU), these options are located under the BIOS/Processor Options. This setting has the following Redfish properties:

/redfish/v1/systems/1/bios/settings/CustomPstate0

/redfish/v1/systems/1/bios/settings/Pstate0Frequency

ROM Flash Firmware Package - HPE ProLiant XL230k Gen10 (U37) Server
Version: 2.76_02-09-2023 (**Recommended**)
Filename: U37_2.76_02_09_2023.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE ProLiant XL230k Gen10 System ROM - U37

Release Version:

2.76_02-09-2023

Last Recommended or Critical Revision:

2.76_02-09-2023

Previous Revision:

2.72_09-29-2022

Firmware Dependencies:

None

Enhancements/New Features:

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Fixes**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-32231 and CVE-2022-26343. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434. This issue is not unique to HPE servers.

Addressed an issue that system will hang when BIOS tries to print a large IML message on POST screen.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Addressed an issue where some Chinese and Japanese translations were missing in RBSU.

Known Issues:

None

Enhancements

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

Important Note!

Important Notes:

None

Deliverable Name:

HPE ProLiant XL645d/XL215n Gen10 Plus System ROM - A48

Release Version:

2.68_02-06-2023

Last Recommended or Critical Revision:

2.68_02-06-2023

Previous Revision:

2.64_11-30-2022

Firmware Dependencies:

None

Enhancements/New Features:

Add new System Configuration (RBSU) configuration options that allow controlling the processors P0 (maximum) frequency. This includes the Custom Pstate0 option with settings of Auto (default) and Manual and the Pstate0 Frequency(MHz) option that allows setting the P0 frequency. When the Custom Pstate0 option is configured for Manual, the value of the Pstate0 Frequency(MHz) is used for the processors P0 frequency. When the Custom Pstate0 option is configured for Auto, the processor uses its normal, maximum P0 frequency and the Pstate0 Frequency(MHz) option is not configurable. In System Configuration (RBSU), these options are located under the BIOS/Processor Options. This setting has the following Redfish properties:

/redfish/v1/systems/1/bios/settings/CustomPstate0

/redfish/v1/systems/1/bios/settings/Pstate0Frequency

Problems Fixed:

This revision of the System ROM updates zlib to 1.2.13 which provides mitigation for BIOS security vulnerability documented as CVE-2022-37434.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-37434>). This security vulnerability is documented in the CVE report site.

This revision of the System ROM includes the v1.1.1s openssl which provides mitigation for BIOS security vulnerability documented as CVE-2022-2097.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-2097>). This security vulnerability is documented in the CVE report site.

Known Issues:

None

Fixes

Important Notes:

None

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM updates zlib to 1.2.13 which provides mitigation for BIOS security vulnerability documented as CVE-2022-37434.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-37434>). This security vulnerability is documented in the CVE report site.

This revision of the System ROM includes the v1.1.1s openssl which provides mitigation for BIOS security vulnerability documented as CVE-2022-2097.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-2097>). This security vulnerability is documented in the CVE report site.

Known Issues:

None

Enhancements

Add new System Configuration (RBSU) configuration options that allow controlling the processors P0 (maximum) frequency. This includes the Custom Pstate0 option with settings of Auto (default) and Manual and the Pstate0 Frequency(MHz) option that allows setting the P0 frequency. When the Custom Pstate0 option is configured for Manual, the value of the Pstate0 Frequency(MHz) is used for the processors P0 frequency. When the Custom Pstate0 option is configured for Auto, the processor uses its normal, maximum P0 frequency and the Pstate0 Frequency(MHz) option is not configurable. In System Configuration (RBSU), these options are located under the BIOS/Processor Options. This setting has the following Redfish properties:

/redfish/v1/systems/1/bios/settings/CustomPstate0

/redfish/v1/systems/1/bios/settings/Pstate0Frequency

ROM Flash Universal Firmware Package - HPE Apollo 6500 Gen10 Plus/HPE ProLiant XL675d Gen10 Plus (A47) Servers

Version: 2.68_02-06-2023 **(Recommended)**

Filename: A47_2.68_02_06_2023.fwpkg

Important Note!**Important Notes:**

None

Deliverable Name:

HPE Apollo 6500 Gen10 Plus/ProLiant XL675d Gen10 Plus System ROM - A47

Release Version:

2.68_02-06-2023

Last Recommended or Critical Revision:

2.68_02-06-2023

Previous Revision:

2.64_11-30-2022

Firmware Dependencies:

None

Enhancements/New Features:

Add new System Configuration (RBSU) configuration options that allow controlling the processors P0 (maximum) frequency. This includes the Custom Pstate0 option with settings of Auto (default) and Manual and the Pstate0 Frequency(MHz) option that allows setting the P0 frequency. When the Custom Pstate0 option is configured for Manual, the value of the Pstate0 Frequency(MHz) is used for the processors P0 frequency. When the Custom Pstate0 option is configured for Auto, the processor uses its normal, maximum P0 frequency and the Pstate0 Frequency(MHz) option is not configurable. In System Configuration (RBSU), these options are located under the BIOS/Processor Options. This setting has the following Redfish properties:

/redfish/v1/systems/1/bios/settings/CustomPstate0

/redfish/v1/systems/1/bios/settings/Pstate0Frequency

Problems Fixed:

This revision of the System ROM updates zlib to 1.2.13 which provides mitigation for BIOS security vulnerability documented as CVE-2022-37434.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-37434>). This security vulnerability is documented in the CVE report site.

This revision of the System ROM includes the v1.1.1s openssl which provides mitigation for BIOS security vulnerability documented as CVE-2022-2097.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-2097>). This security vulnerability is documented in the CVE report site.

Known Issues:

None

Fixes

Important Notes:

None

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM updates zlib to 1.2.13 which provides mitigation for BIOS security vulnerability documented as CVE-2022-37434.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-37434>). This security vulnerability is documented in the CVE report site.

This revision of the System ROM includes the v1.1.1s openssl which provides mitigation for BIOS security vulnerability documented as CVE-2022-2097.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-2097>). This security vulnerability is documented in the CVE report site.

Known Issues:

None

Enhancements

Add new System Configuration (RBSU) configuration options that allow controlling the processors P0 (maximum) frequency. This includes the Custom Pstate0 option with settings of Auto (default) and Manual and the Pstate0 Frequency(MHz) option that allows setting the P0 frequency. When the Custom Pstate0 option is configured for Manual, the value of the Pstate0 Frequency(MHz) is used for the processors P0 frequency. When the Custom Pstate0 option is configured for Auto, the processor uses its normal, maximum P0 frequency and the Pstate0 Frequency(MHz) option is not configurable. In System Configuration (RBSU), these options are located under the BIOS/Processor Options. This setting has the following Redfish properties:

/redfish/v1/systems/1/bios/settings/CustomPstate0

/redfish/v1/systems/1/bios/settings/Pstate0Frequency

ROM Flash Universal Firmware Package - HPE ProLiant DL325/DL325 v2/DL345 Gen10 Plus (A43) Servers

Version: 2.68_02-06-2023 (**Recommended**)

Filename: A43_2.68_02_06_2023.fwpkg

Important Note!**Important Notes:**

None

Deliverable Name:

HPE ProLiant DL325/DL325 v2/DL345 Gen10 Plus System ROM - A43

Release Version:

2.68_02-06-2023

Last Recommended or Critical Revision:

2.68_02-06-2023

Previous Revision:

2.64_11-17-2022

Firmware Dependencies:

None

Enhancements/New Features:

Add new System Configuration (RBSU) configuration options that allow controlling the processors P0 (maximum) frequency. This includes the Custom Pstate0 option with settings of Auto (default) and Manual and the Pstate0 Frequency(MHz) option that allows setting the P0 frequency. When the Custom Pstate0 option is configured for Manual, the value of the Pstate0 Frequency(MHz) is used for the processors P0 frequency. When the Custom Pstate0 option is configured for Auto, the processor uses its normal, maximum P0 frequency and the Pstate0 Frequency(MHz) option is not configurable. In System Configuration (RBSU), these options are located under the BIOS/Processor Options. This setting has the following Redfish properties:

/redfish/v1/systems/1/bios/settings/CustomPstate0

/redfish/v1/systems/1/bios/settings/Pstate0Frequency

Problems Fixed:

This revision of the System ROM updates zlib to 1.2.13 which provides mitigation for BIOS security vulnerability documented as CVE-2022-37434.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-37434>). This security vulnerability is documented in the CVE report site.

This revision of the System ROM includes the v1.1.1s openssl which provides mitigation for BIOS security vulnerability documented as CVE-2022-2097.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-2097>). This security vulnerability is documented in the CVE report site.

Known Issues:

None

Fixes**Important Notes:**

None

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM updates zlib to 1.2.13 which provides mitigation for BIOS security vulnerability documented as CVE-2022-37434.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-37434>). This security vulnerability is documented in the CVE report site.

This revision of the System ROM includes the v1.1.1s openssl which provides mitigation for BIOS security vulnerability documented as CVE-2022-2097.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-2097>). This security vulnerability is documented in the CVE report site.

Known Issues:

None

Enhancements

Add new System Configuration (RBSU) configuration options that allow controlling the processors P0 (maximum) frequency. This includes the Custom Pstate0 option with settings of Auto (default) and Manual and the Pstate0 Frequency(MHz) option that allows setting the P0 frequency. When the Custom Pstate0 option is configured for Manual, the value of the Pstate0 Frequency(MHz) is used for the processors P0 frequency. When the Custom Pstate0 option is configured for Auto, the processor uses its normal, maximum P0 frequency and the Pstate0 Frequency(MHz) option is not configurable. In System Configuration (RBSU), these options are located under the BIOS/Processor Options. This setting has the following Redfish properties:

/redfish/v1/systems/1/bios/settings/CustomPstate0

/redfish/v1/systems/1/bios/settings/Pstate0Frequency

ROM Flash Universal Firmware Package - HPE ProLiant DL360/DL380 Gen10 Plus (U46) Servers

Version: 1.72_02-02-2023 **(Recommended)**

Filename: U46_1.72_02_02_2023.fwpkg

Important Note!**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Deliverable Name:

HPE DL360 Gen10 Plus/DL380 Gen10 Plus System ROM - U46

Release Version:

1.72_02-02-2023

Last Recommended or Critical Revision:

1.72_02-02-2023

Previous Revision:

1.68_10-27-2022

Firmware Dependencies:

None

Enhancements/New Features:

Added "Important: Intel(R) NVMe and Intel(R) VROC are not supported when the Boot Mode is configured in Legacy BIOS Mode." message into the RBSU help description for Intel NVMe VROC option.

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

Downgraded several debug messages from DEBUG_ERROR to DEBUG_INFO level. Removed unnecessary error messages in BIOS serial log.

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-21216, CVE-2022-32231, CVE-2022-26343, CVE-2022-33196, CVE-2022-38090 and CVE-2022-33972. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1s update which provides mitigation for security vulnerabilities documented as CVE-2022-2097.

Addressed an issue where the controller name was not displayed in Japanese when MegaRAID was switched to Japanese, .

Addressed an issue where NVMe drive info was not displayed properly in iLO when Intel PCH VMD is enabled in RBSU.

Addressed an issue where Intel VROC SATA firmware shows N/A under PCI Device information.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Known Issues:

None

Fixes**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.1 guidance.

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM includes the latest revision of the Intel IPU 2023.1 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-21216, CVE-2022-32231, CVE-2022-26343, CVE-2022-33196, CVE-2022-38090 and CVE-2022-33972. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the zlib library 1.2.13 update which provides mitigation for and security vulnerabilities documented as CVE-2022-37434.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1s update which provides mitigation for security vulnerabilities documented as CVE-2022-2097.

Addressed an issue where the controller name was not displayed in Japanese when MegaRAID was switched to Japanese, .

Addressed an issue where NVMe drive info was not displayed properly in iLO when Intel PCH VMD is enabled in RBSU.

Addressed an issue where Intel VROC SATA firmware shows N/A under PCI Device information.

Addressed an issue when system discovers thousands of LUNs and was trying to create thousands of boot options for each LUNs. System cannot add, delete or adjust new boot options on iLO web and RBSU after rebooting. System becomes unstable unless loading manufacture default.

Known Issues:

None

Enhancements

Added "Important: Intel(R) NVMe and Intel(R) VROC are not supported when the Boot Mode is configured in Legacy BIOS Mode." message into the RBSU help description for Intel NVMe VROC option.

Added new System Configuration (RBSU) configuration options that allow enabling and disabling EPP (Energy Performance Preference) when "Workload Profile" sets to "Custom" and "Power Regulator" sets to "OS Control Mode".

Downgraded several debug messages from DEBUG_ERROR to DEBUG_INFO level. Removed unnecessary error messages in BIOS serial log.

ROM Flash Universal Firmware Package - HPE ProLiant DL365/DL385/DL385 v2 Gen10 Plus (A42) Servers
Version: 2.68_02-06-2023 (**Recommended**)
Filename: A42_2.68_02_06_2023.fwpkg

Important Note!

Important Notes:

None

Deliverable Name:

HPE DL365 Gen10 Plus/DL385 Gen10 Plus/DL385 v2 Gen10 Plus System ROM - A42

Release Version:

2.68_02-06-2023

Last Recommended or Critical Revision:

2.68_02-06-2023

Previous Revision:

2.64_11-17-2022

Firmware Dependencies:

None

Enhancements/New Features:

Add new System Configuration (RBSU) configuration options that allow controlling the processor's P0 (maximum) frequency. This includes the "Custom Pstate0" option with settings of "Auto" (default) and "Manual" and the "Pstate0 Frequency(MHz)" option that allows setting the P0 frequency. When the "Custom Pstate0" option is configured for "Manual", the value of the "Pstate0 Frequency(MHz)" is used for the processor's P0 frequency. When the "Custom Pstate0" option is configured for "Auto", the processor uses its normal, maximum P0 frequency and the "Pstate0 Frequency(MHz)" option is not configurable. In System Configuration (RBSU), these options are located under the BIOS/Processor Options. This setting has the following Redfish properties:

/redfish/v1/systems/1/bios/settings/CustomPstate0

/redfish/v1/systems/1/bios/settings/Pstate0Frequency

Problems Fixed:

This revision of the System ROM updates zlib to 1.2.13 which provides mitigation for BIOS security vulnerability documented as CVE-2022-37434.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-37434>). This security vulnerability is documented in the CVE report site.

This revision of the System ROM includes the v1.1.1s openssl which provides mitigation for BIOS security vulnerability documented as CVE-2022-2097.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-2097>). This security vulnerability is documented in the CVE report site.

Known Issues:

None

Fixes

Important Notes:

None

Firmware Dependencies:

None

Problems Fixed:

This revision of the System ROM updates zlib to 1.2.13 which provides mitigation for BIOS security vulnerability documented as CVE-2022-37434.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-37434>). This security vulnerability is documented in the CVE report site.

This revision of the System ROM includes the v1.1.1s openssl which provides mitigation for BIOS security vulnerability documented as CVE-2022-2097.

(<https://nvd.nist.gov/vuln/detail/CVE-2022-2097>). This security vulnerability is documented in the CVE report site.

Known Issues:

None

Enhancements

Add new System Configuration (RBSU) configuration options that allow controlling the processor's P0 (maximum) frequency. This includes the "Custom Pstate0" option with settings of "Auto" (default) and "Manual" and the "Pstate0 Frequency(MHz)" option that allows setting the P0 frequency. When the "Custom Pstate0" option is configured for "Manual", the value of the "Pstate0 Frequency(MHz)" is used for the processor's P0 frequency. When the "Custom Pstate0" option is configured for "Auto", the processor uses its normal, maximum P0 frequency and the "Pstate0 Frequency(MHz)" option is not configurable. In System Configuration (RBSU), these options are located under the BIOS/Processor Options. This setting has the following Redfish properties:

`/redfish/v1/systems/1/bios/settings/CustomPstate0`

`/redfish/v1/systems/1/bios/settings/Pstate0Frequency`

Driver - Lights-Out Management [Top](#)

HPE iLO Native Driver for ESXi 7.0

Version: 10.8.0 (**Recommended**)

Filename: ilo-driver_700.10.8.0.6-1OEM.700.1.0.15843807_20300719.zip

Fixes

- Fixed issue where ilo driver is failing to acquire contiguous physical memory below 4GB causing userworld apps like hponcfg to be unable to communicate with iLO.

Enhancements

- Added support for vSphere 8.0

Driver - Network [Top](#)

HPE Broadcom NetXtreme-E Drivers for VMware vSphere 7.0

Version: 2023.03.00 (**Recommended**)

Filename: cp054746.compsig; cp054746.zip

Important Note!

- This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.
- HPE recommends the *HPE Broadcom NetXtreme-E Firmware Version*, 224.1.102000 or later, for use with this driver.

Fixes

- This product correct an issue which Fix no VLAN stripping issue.
- This product correct an issue which Invalid memory access when DCB structure memory allocation fails during driver unload and DCB async event received by driver.

Enhancements

- This product enhances queue deletion and addition support ENS driver for VMware NSX-T.
- This product enhances to support for PHY_CFG_CHANGE event processing, driver receives async event for any change in

pause behavior.

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 535FLR-T Adapter
- HPE Ethernet 10Gb 2-port 535T Adapter
- HPE Ethernet 10Gb 2-port 537SFP+ Adapter
- HPE Ethernet 10Gb 2-port 537SFP+ FLR Adapter
- HPE Ethernet 10/25Gb 2-port 631FLR-SFP28 Adapter
- HPE Ethernet 10/25Gb 2-port 631SFP28 Adapter
- HPE Ethernet 10Gb 2-port SFP+ BCM57412 OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ BCM57412 Adapter
- HPE Ethernet 10Gb 2-port BaseT BCM57416 OCP3 Adapter
- HPE Ethernet 10Gb 2-port BaseT BCM57416 Adapter
- HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 OCP3 Adapter
- HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 Adapter
- Broadcom BCM57504 Ethernet 10/25Gb 4-port SFP28 Adapter for HPE
- Broadcom BCM57504 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter for HPE

HPE Intel i40en Driver for VMware vSphere 7.0

Version: 2023.03.00 (**Recommended**)

Filename: cp054593.compsig; cp054593.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for VMware*, version 3.20.0 or later, for use with this driver.

Enhancements

This product enhanced the compatibility with firmware of FVL9.1.

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 1Gb 2-port 368FLR-MMT Adapter
- HPE Ethernet 1Gb 2-port 368i Adapter
- HPE Ethernet 1Gb 4-port 369i Adapter
- HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 562SFP+ Adapter
- HPE Ethernet 10Gb 2-port 563i Adapter
- HPE Ethernet 10Gb 2-port 568FLR-MMSFP+ Adapter
- HPE Ethernet 10Gb 2-port 568FLR-MMT Adapter
- HPE Ethernet 10Gb 2-port 568i Adapter
- HPE Ethernet 10Gb 2-port SFP+ OCP3 X710-DA2 Adapter
- HPE Ethernet 10Gb 2-port SFP+ X710-DA2 Adapter

HPE Intel igbn Driver for VMware vSphere 7.0

Version: 2023.03.00 (**Recommended**)

Filename: cp055476.compsig; cp055476.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for VMware*, version 3.20.0 or later, for use with this driver.

Enhancements

This product now supports the following new server.

HPE ProLiant DL560 Gen11 Server
HPE ProLiant DL110 Gen11 Server
HPE ProLiant ML110 Gen11 Server

Supported Devices and Features

These drivers support the following network adapters:

- HPE Ethernet 1Gb 2-port 361T Adapter
- HPE Ethernet 1Gb 2-port 361i Adapter
- HPE Ethernet 1Gb 2-port 363i Adapter
- HPE Ethernet 1Gb 4-port 366FLR Adapter
- HPE Ethernet 1Gb 4-port 366T Adapter
- HPE Ethernet 1Gb 4-port 366i Adapter
- HPE Ethernet 1Gb 4-port 366i Communication Board
- Intel I350-T4 Ethernet 1Gb 4-port BASE-T Adapter for HPE
- Intel I350-T4 Ethernet 1Gb 4-port BASE-T OCP3 Adapter for HPE
- Intel(R) I350 Gigabit Network Connection

HPE Intel ixgben Driver for VMware vSphere 7.0
Version: 2023.03.00 (**Recommended**)
Filename: cp054594.compsig; cp054594.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for VMware*, version 3.2.0 or later, for use with this driver.

Enhancements

This product enhanced the compatibility with new version of the firmware.

Supported Devices and Features

These drivers support the following network adapters:

- HPE Ethernet 10Gb 2-port 560SFP+ Adapter
- HPE Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 561T Adapter
- HPE Ethernet 10Gb 2-port 561FLR-T Adapter
- HPE Ethernet 10Gb 2-port 562T Adapter
- HPE Ethernet 10Gb 2-port 562FLR-T Adapter

HPE QLogic FastLinQ 10/25/50 GbE Multifunction Driver for VMware vSphere 7.0
Version: 2023.03.00 (**Recommended**)
Filename: cp055118.compsig; cp055118.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided as below for use with these drivers,

- HPE QLogic FastLinQ Firmware Package for Arrowhead adapters, version 8.65.01 or later.
- HPE QLogic FastLinQ Online Firmware Upgrade Utility for VMware, version 4.17.0 or later.

Enhancements

This product synchronizes FW Upgrade Utility version with VMware version

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 521T Adapter
- HPE Ethernet 10Gb 2-port 524SFP+ Adapter

- HPE Ethernet 10/25Gb 2-port 621SFP28 Adapter
- HPE Ethernet 10/25Gb 2-port 622FLR-SFP28 Converged Network Adapter
- HPE StoreFabric CN1200R-T Converged Network Adapter
- HPE StoreFabric CN1300R Converged Network Adapter
- HPE Ethernet 10/25Gb 2-port SFP28 QL41232HQCUC OCP3 Adapter
- HPE Ethernet 10/25Gb 2-port SFP28 QL41232HLCU Adapter
- HPE Ethernet 10Gb 4-port SFP+ QL41134HLCU Adapter
- HPE Ethernet 10Gb 2-port BaseT QL41132HLRJ Adapter
- HPE Ethernet 10Gb 2-port BaseT QL41132HQRJ OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ QL41132HQCUC OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ QL41132HLCU Adapter

HPE QLogic NX2 10/20 GbE Multifunction Driver for VMware vSphere 7.0

Version: 2022.09.01 (**Recommended**)

Filename: cp050968.compsig; cp050968.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hp.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided in *HPE QLogic NX2 Online Firmware Upgrade Utility for VMware*, version 1.31.0 or later, for use with this driver.

Fixes

- This product correct an issue which System crashed with PSOD upon clean reboot.
- This product correct an issue which Physical link LED still ON even after esxcli down.
- This product correct an issue which PSOD occurred while querying adapters with esxcli plugin.
- This product correct an issue which recursive panic occurs when capturing VM-Support dump.

Enhancements

This product is updated to maintain compatibility with CNSA (Commercial National Security Algorithm) compliance.

Supported Devices and Features

These drivers support the following network adapters:

- HPE Ethernet 10Gb 2-port 530T Adapter
- HPE Ethernet 10Gb 2-port 530SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 533FLR-T Adapter
- HPE FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HPE StoreFabric CN1100R Dual Port Converged Network Adapter
- HPE StoreFabric CN1100R 10GBASE-T Dual Port Converged Network Adapter

Intel icen Driver for VMware vSphere 7.0

Version: 2023.03.00 (**Recommended**)

Filename: cp055475.compsig; cp055475.zip

Important Note!

- This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.
- HPE recommends the firmware provided in *Intel Firmware Package For E810 Ethernet Adapter*, version 4.10 or later, for use with this driver.

Enhancements

This product enhanced the compatibility with firmware of CVL4.1.

Supported Devices and Features

This product supports the following network adapters:

- Intel E810-CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter for HPE
- Intel E810-CQDA2 Ethernet 100Gb 2-port QSFP28 OCP3 Adapter for HPE
- Intel E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 Adapter for HPE

- Intel E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 Adapter for HPE
- Intel E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE
- Intel E810-2CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter for HPE
- Intel E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter for HPE

Mellanox ConnectX-4, ConnectX-5 and ConnectX-6 "nmlx5_en" Driver Component for VMware ESXi 7.0 Update 3
 Version: 2022.11.09 (**Recommended**)
 Filename: cp054875.compsig; cp054875.zip

Important Note!

Important: Version 4.22.73.1004 supports VMware ESXi 7.0 Update 3 only.

Known Issues with driver version 4.22.73.1004:

- A mismatch between the uplink and the VF MTU values may result in CQE with error.
Workaround: Align the uplink and the VF MTU values.
- Enabling sriov_mc_isolation module parameter may result in vmknic and emulated NICs multicast and IPv6 traffic loss.
Workaround: Unset or set the module parameter to 0.
- RDMA is not supported in the Hypervisor with ENS (Enhanced Network Stack) model 2.
- Setting the "Allow Guest MTU Change" option in vSphere Client is currently not functional. Although guest MTU changes in SR-IOV are allowed, they do not affect the port's MTU and the guest's MTU remains the same as the PF MTU.
- ECN (Explicit congestion notification) statistic counters accumulatorsPeriod and ecnMarkedRocePackets display wrong values and cannot be cleared.
- ECN tunable parameter initialAlphaValue for the Reaction Point protocol cannot be modified.
- Card's speed remains zero after port goes down and reboot is performed.
- RoCE traffic may fail after vMotion when using namespace.
- Legacy SR-IOV is not supported with Model 1.
- When in ENS mode, changing the scheduler to HCLK, may cause traffic loss.
- The 'esxcli mellanox uplink link info -u <vmnic_name>' command reports the 'Auto negotiation' capability always as 'true'.
- SMP MADs (ibnetdiscover, sminfo, iblinkinfo, smpdump, ibqueryerr, ibdiagnet and smpquery) are not supported on the VFs.
- Although the max_vfs module parameter range is "0-128", due to firmware limitations, the following are the supported VFs per single port devices:
 - ConnectX-4 / ConnectX-5: up to 127

Fixes

Fixes included in driver version 4.22.73.1004:

- Fixed an issue that caused a ParaVirtual VM to lose traffic after resuming from the suspend mode when SR-IOV was enabled in the system.
- Cleaned steering rule from FDB when VF is being quiesced.
- Fixed an issue that caused the driver to configure the incorrect SL value for RoCE with RDMACM.

Enhancements

New features and changes in driver version 4.22.73.1004:

- Firmware CR dump will now be collected automatically into ZDUMP PSOD or on livedump for debuggability purposes.
- Enabled the driver to read the temperature from private statistics.

To see the temperature, run: `# nsxudp-cli ens uplink stats get -n vmnic1 | grep -i asicSensorTemperature`

- Added support for Hardware Accelerated GENEVE and VXLAN encapsulation and decapsulation for RoCE traffic.
- Hardware accelerated flows can now be mirrored using the standard packet capture tools.
- Added the ability to offload NSX Distributed Firewall rules by using in-hardware tracking of packet flows.
- RSS support for ENS Model 1 improves performance using fewer CPU cores. This capability can be enabled using the "netq_rss_ens" module parameter.

Supported Devices and Features

HPE Part Number	Device Name	PSID
P24837-B21	HPE Ethernet 10/25Gb 2-port 642SFP28 Adapter	HPE0000000054
P11338-B21	HPE Ethernet 10Gb 2-port 548SFP+ Adapter	HP_1200111023
825110-B21	HPE InfiniBand EDR/Ethernet 100Gb 1-port 840QSFP28 Adapter	HP_2180110032
825111-B21	HPE InfiniBand EDR/Ethernet 100Gb 2-port 840QSFP28 Adapter	HP_2190110032
872726-B21	HPE InfiniBand EDR/Ethernet 100Gb 2-port 841QSFP28 Adapter	HPE0000000009
879482-B21	HPE InfiniBand FDR/Ethernet 40/50Gb 2-port 547FLR-QSFP Adapter	HPE0000000022

817749-B21	HPE Ethernet 10/25Gb 2-port FLR-SFP28 MCX4121A-ACFT Adapter	HP_2690110034
817753-B21	HPE Ethernet 10/25Gb 2-port SFP28 MCX4121A-ACUT Adapter	HP_2420110034
P21927-B21	HPE Ethernet 100Gb 2-port QSFP28 MCX516A-CCHT Adapter	MT_0000000417
P10112-B21	Mellanox MCX562A-ACAI Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE	MT_0000000241
P13188-B21	Mellanox MCX512F-ACHT Ethernet 10/25Gb 2-port SFP28 Adapter for HPE	MT_0000000416
P11341-B21	HPE Ethernet 10Gb 2-port SFP+ MCX4621A-ACAB OCP3 Adapter	MT_0000000238
P21930-B21	HPE Ethernet 10Gb 2-port SFP+ MCX4121A-XCHT Adapter	MT_0000000414
874253-B21	HPE Ethernet 100Gb 1-port QSFP28 MCX515A-CCAT Adapter	HPE0000000014
P25960-B21	Mellanox MCX623106AS-CDAT Ethernet 100Gb 2-port QSFP56 Adapter for HPE	MT_0000000437
P06154-B21	HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe3 x16 MCX653105A-HDAT Adapter	HPE0000000034
P06250-B21	HPE InfiniBand HDR100/Ethernet 100Gb 1-port QSFP56 PCIe3 x16 MCX653105A-ECAT Adapter	HPE0000000035
P06251-B21	HPE InfiniBand HDR100/Ethernet 100Gb 2-port QSFP56 PCIe3 x16 MCX653106A-ECAT Adapter	HPE0000000036
P23664-B21	HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 MCX653105A-HDAT Adapter	MT_0000000451
P23665-B21	HPE InfiniBand HDR100/Ethernet 100Gb 1-port QSFP56 PCIe4 x16 MCX653105A-ECAT Adapter	MT_0000000452
P23666-B21	HPE InfiniBand HDR100/Ethernet 100Gb 2-port QSFP56 PCIe4 x16 MCX653106A-ECAT Adapter	MT_0000000453
P10180-B21	Mellanox MCX623105AS-VDAT Ethernet 200Gb 1-port QSFP56 Adapter for HPE	MT_0000000435
P31246-B21	HPE Ethernet 100Gb 1-port QSFP28 PCIe3 x16 MCX515A-CCAT Adapter	MT_0000000591
P31323-B21	HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 OCP3 MCX653435A-HDAI Adapter	MT_0000000592
P31348-B21	HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 OCP3 MCX653436A-HDAI Adapter	MT_0000000593
P31324-B21	HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 MCX653106A-HDAT Adapter	MT_0000000594
P42041-B21	Mellanox MCX631432AS-ADAI Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE	MT_0000000551
P42044-B21	Mellanox MCX631102AS-ADAT Ethernet 10/25Gb 2-port SFP28 Adapter for HPE	MT_0000000575

net-mst kernel module driver component for VMware ESXi 7.0
Version: 2020.11.11 (D) **(Recommended)**
Filename: cp052137.compsig; cp052137.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the HPE vib depot.hpe.com webpage, plus an HPE specific CPXXXX.xml file.

Prerequisites

NA

Enhancements

The following changes have been made in sub-version 2020.11.11(D):

- o Product rebuilt to have the new SHA 384 signature.
- o Removed support for the following servers:
 - Blade servers BLxxxx Gen9/Gen10 series.

Supported Devices and Features

HPE Part Number	Device Name	PSID
764282-B21	HPE InfiniBand QDR/Ethernet 10Gb 2-port 544+M Adapter	HP_1350110023
764283-B21	HPE InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+M Adapter	HP_1360110017
764284-B21	HPE InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+QSFP Adapter	HP_1370110017
P24837-B21	HPE Ethernet 10/25Gb 2-port 642SFP28 Adapter	HPE0000000054

P11338-B21	HPE Ethernet 10Gb 2-port 548SFP+ Adapter	HP_1200111023
764285-B21	HPE InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+FLR-QSFP Adapter	HP_1380110017
764286-B21	HPE InfiniBand QDR/Ethernet 10Gb 2-port 544+FLR-QSFP Adapter	HP_1390110023
825110-B21	HPE InfiniBand EDR/Ethernet 100Gb 1-port 840QSFP28 Adapter	HP_2180110032
825111-B21	HPE InfiniBand EDR/Ethernet 100Gb 2-port 840QSFP28 Adapter	HP_2190110032
872726-B21	HPE InfiniBand EDR/Ethernet 100Gb 2-port 841QSFP28 Adapter	HPE000000009
879482-B21	HPE InfiniBand FDR/Ethernet 40/50Gb 2-port 547FLR-QSFP Adapter	HPE000000022
868779-B21	HPE Synergy 6410C 25/50Gb Ethernet Adapter	HPE000000006
779793-B21	HPE Ethernet 10Gb 2-port 546SFP+ Adapter	HP_1200111023
779799-B21	HPE Ethernet 10Gb 2-port 546FLR-SFP+ Adapter	HP_2240110004
817749-B21	HPE Ethernet 25Gb 2-port 640FLR-SFP28 Adapter	HP_2690110034
817753-B21	HPE Ethernet 25Gb 2-port 640SFP28 Adapter	HP_2420110034
P21927-B21	HPE Ethernet 100Gb 2-port QSFP28 MCX516A-CCHT Adapter	MT_0000000417
P10112-B21	HPE Ethernet 10/25Gb 2-port SFP28 MCX562A-ACAI OCP3 Adapter	MT_0000000241
P13188-B21	HPE Ethernet 10/25Gb 2-port SFP28 MCX512F-ACHT Adapter	MT_0000000416
P11341-B21	HPE Ethernet 10Gb 2-port SFP+ MCX4621A-ACAB OCP3 Adapter	MT_0000000238
P21930-B21	HPE Ethernet 10Gb 2-port SFP+ MCX4121A-XCHT Adapter	MT_0000000414
874253-B21	HPE Ethernet 100Gb 1-port 842QSFP28 Adapter	HPE000000014
P25960-B21	HPE Ethernet 100Gb 2-Port QSFP56 MCX623106AS-CDAT Adapter	MT_0000000437
P06154-B21	HPE InfiniBand HDR/Ethernet 200Gb 1-port 940QSFP56 x16 Adapter	HPE000000034
P06250-B21	HPE InfiniBand HDR100/Ethernet 100Gb 1-port 940QSFP56 x16 Adapter	HPE000000035
P06251-B21	HPE InfiniBand HDR100/Ethernet 100Gb 2-port 940QSFP56 x16 Adapter	HPE000000036
P23664-B21	HPE InfiniBand HDR/Ethernet 200Gb 1-port MCX653105A-HDAT QSFP56 x16 Adapter	MT_0000000451
P23665-B21	HPE InfiniBand HDR100/Ethernet 100Gb 1-port MCX653105A-ECAT QSFP56 x16 Adapter	MT_0000000452
P23666-B21	HPE InfiniBand HDR100/Ethernet 100Gb 2-port MCX653106A-ECAT QSFP56 x16 Adapter	MT_0000000453
P10180-B21	Mellanox MCX623105AS-VDAT Ethernet 200Gb 1-port QSFP56 Adapter for HPE	MT_0000000435
P31246-B21	HPE Ethernet 100Gb 1-port QSFP28 PCIe3 x16 MCX515A-CCAT Adapter	MT_0000000591
P31323-B21	HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 OCP3 MCX653435A-HDAI Adapter	MT_0000000592
P31348-B21	HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 OCP3 MCX653436A-HDAI Adapter	MT_0000000593
P31324-B21	HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 MCX653106A-HDAT Adapter	MT_0000000594
P42041-B21	Mellanox MCX631432AS-ADAI Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE	MT_0000000551
P42044-B21	Mellanox MCX631102AS-ADAT Ethernet 10/25Gb 2-port SFP28 Adapter for HPE	MT_0000000575

nmlx4_en Driver Component for VMware 7.0
Version: 2020.11.11 (B) (**Recommended**)
Filename: cp053712.compsig; cp053712.zip

Important Note!

Known Issues:

- ConnectX-3 Pro 10G adapter cards incorrectly report support for 40G speed when running the "esxcli network nic get" command.
- When the port is DOWN, the management interface "port type" field indicates one of the port types supported by the device, in the following order: TP, FIBER, DA, NONE. If the port supports several cable types, the first type in the list mentioned above will be printed.
- When the port is UP, the management interface port type field (nmlx_en_MgmtIFPortType) indicates which one of all possible supported types is currently connected.
- Management interface port type field reports SFP-to-RJ45 cable as FIBER.
- Management interface auto negotiation field is equivalent to "esxcli network nic get -n vmnicX" field "Pause Autonegotiate".

For further information on the release notes for ESXi 7.0 Driver Version 3.19.70.1 follow the below link:
https://www.mellanox.com/page/products_dyn?product_family=29&mtag=vmware_driver

Fixes

No fixes are included in version 3.19.70.1:

Enhancements

The following changes have been made in sub-version 2020.11.11(B):

- Product rebuilt to have the new SHA 384 signature.

Changes and New Features in version 3.19.70.1:

- Resolved an issue that caused the network adapter traffic to stop.
- Fixed an internal multicast loopback issue that broke LACP(Link Aggregation Control Protocol) bonding protocol.

Supported Devices and Features

HPE Part Number	Device Name	PSID
764282-B21	HPE InfiniBand QDR/Ethernet 10Gb 2-port 544+M Adapter	HP_1350110023
764283-B21	HPE InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+M Adapter	HP_1360110017
764284-B21	HPE InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+QSFP Adapter	HP_1370110017
764285-B21	HPE InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+FLR-QSFP Adapter	HP_1380110017
764286-B21	HPE InfiniBand QDR/Ethernet 10Gb 2-port 544+FLR-QSFP Adapter	HP_1390110023
779793-B21	HPE Ethernet 10Gb 2-port 546SFP+ Adapter	HP_1200111023
779799-B21	HPE Ethernet 10Gb 2-port 546FLR-SFP+ Adapter	HP_2240110004

VMware ESXi 7.0 MST Drivers Offline Bundle for Mellanox Adapters

Version: 4.14.3.3 (**Recommended**)

Filename: Mellanox-NATIVE-NMST_4.14.3.3-1OEM.700.1.0.15525992_16211416.zip

Prerequisites

NA

Enhancements

VM70 nmst 4.14.3.3

Driver - Storage Controller

[Top](#)

HPE Gen10 Smart Array and Gen10 Plus/Gen11 Smart RAID Controller Driver for VMware vSphere 7.0 (Driver Component).

Version: 2023.04.01 (**Recommended**)

Filename: cp055511.compsig; cp055511.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com, plus an HPE specific CPXXXX.xml file.

Enhancements

Support ML110 and DL560 Gen11 servers

HPE MR416i-a, MR416i-p, MR216i-a, MR216i-p, MR416i-o controller (64-bit) Driver for vSphere 7.0

Version: 7.722.02.00 (B) (**Recommended**)

Filename: Broadcom-lsi-mr3_7.722.02.00-1OEM.700.1.0.15843807_20225841.zip

Enhancements

Gen11 PR2 Usage

HPE MR416i-p, MR416i-o, MR216i-o, MR408i-o, MR216i-p Gen10P and Gen11 controller (64-bit) Driver for vSphere 7.0

Version: 2023.04.01 (**Recommended**)

Filename: cp055449.compsig; cp055449.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CPXXXX.xml file.

Enhancements

Support HPE ML110 and DL560 Gen11 servers

Firmware - Network

Broadcom Firmware Package for BCM5741x adapters

Version: 224.1.102.0 **(Recommended)**

Filename: bcm224.1.102.0.pup.fwpkg

[Top](#)

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Broadcom NetXtreme-E Driver for Microsoft Windows Server, version 224.0.159.0 or later
- HPE Broadcom NetXtreme-E Drivers for Linux, version 1.10.2-224.0.157.0 or later
- HPE Broadcom NetXtreme-E Drivers for VMware, version 2023.03.00 or later

Fixes

- This product correct an issue which Fix incorrect reset reason for error recovery.
- This product correct an issue which Fix port ID in the odata.id of Port Redfish was always 0.
- This product correct an issue which Write to RDE Port Enabled property request was processed but the handler function was not called.
- This product correct an issue which Unsolicited LLDP shutdown PDU with blank information (including MAC address) was sent on a port where LLDP was disabled.(PDU = LLDP protocol data units)
- This product correct an issue which Firmware failed to NAK invalid TID values (Traffic Identifier)
- This product correct an issue which Firmware reset if there is pending nvm parameter changes.

Enhancements

This product enhances to support for LLDP read/write RDE commands.

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port SFP+ BCM57412 Adapter
- HPE Ethernet 10Gb 2-port SFP+ BCM57412 OCP3 Adapter
- HPE Ethernet 10Gb 2-port BaseT BCM57416 Adapter
- HPE Ethernet 10Gb 2-port BaseT BCM57416 OCP3 Adapter
- HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 Adapter
- HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 OCP3 Adapter

Broadcom Firmware Package for BCM5750x adapters

Version: 224.1.102.0 **(Recommended)**

Filename: bcm224.1.102.0_Thor.pup.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Broadcom NetXtreme-E Driver for Microsoft Windows Server, version 224.0.159.0 or later
- HPE Broadcom NetXtreme-E Drivers for Linux, version 1.10.2-224.0.157.0 or later
- HPE Broadcom NetXtreme-E Drivers for VMware, version 2023.03.00 or later

Fixes

- This product correct an issue which writing MAC addresses to the factory config could error out claiming corruption.
- This product correct an issue which not allow the user to configure the multi-function mode option with option value string.

Enhancements

- This product enhances coredump support to dump cache contents.
- This product enhances Firmware command line module modularity
- This product enhances to add support for disabling Overflow detection for CQs (Completion Queues) of RoCE (RDMA over

converged Ethernet)

- This product enhances FW support for QUIC key (Quick UDP Internet Connection) context backing store management
- This product enhances to add support for PCIe TPH (TLP Processing Hints)

Supported Devices and Features

This product supports the following network adapters:

- Broadcom BCM57504 Ethernet 10/25Gb 4-port SFP28 Adapter for HPE
- Broadcom BCM57504 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter for HPE

Broadcom NX1 Online Firmware Upgrade Utility for VMware

Version: 1.33.2 (**Recommended**)

Filename: CP054668.compsig; CP054668.zip

Important Note!

This software package contains combo image v20.24.41 with the following firmware versions:

NIC	Boot Code Version	PXE Version	NCSI Version	UEFI Version	CCM Version
BCM 5719 1GbE 4p BASE-T Adptr	1.46	21.6.2	1.5.42	21.6.43	224.0.155.0
BCM 5719 1GbE 4p BASE-T OCP3 Adptr	1.46	21.6.2	1.5.42	21.6.43	224.0.155.0
BCM 5720 1GbE 2p BASE-T LOM Adptr	1.42	21.6.2	1.5.42	21.6.43	224.0.155.0

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Fixes

This product correct an issue which the Boot Code Version of the Firmware did not get updated after upgrading the Firmware.

Enhancements

- This product enhances the FW Library to support the second NVRAM type.
- This product now supports ESXi8.0

Supported Devices and Features

This product supports the following network adapters:

- Broadcom BCM5720 Ethernet 1Gb 2-port BASE-T LOM Adapter for HPE
- Broadcom BCM5719 Ethernet 1Gb 4-port Base-T Adapter for HPE
- Broadcom BCM5719 Ethernet 1Gb 4-port Base-T OCP3 Adapter for HPE

HPE Broadcom NetXtreme-E Firmware Package for BCM5741x adapters

Version: 224.1.102000 (**Recommended**)

Filename: bcm224.1.102000.Optimized.pup.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- HPE Broadcom NetXtreme-E Drivers for Windows Server , version 224.0.159.0 or later
- HPE Broadcom NetXtreme-E Drivers for Linux, version 1.10.2-224.0.157.0 or later
- HPE Broadcom NetXtreme-E Drivers for VMware, version 2023.03.00 or later

Fixes

- This product correct an issue which Fix incorrect reset reason for error recovery.
- This product correct an issue which Fix port ID in the odata.id of Port Redfish was always 0.
- This product correct an issue which Write to RDE Port Enabled property request was processed but the handler function was not called.
- This product correct an issue which Unsolicited LLDP shutdown PDU with blank information (including MAC address) was sent

on a port where LLDP was disabled.(PDU = LLDP protocol data units)

- o This product correct an issue which Firmware failed to NAK invalid TID values (Traffic Identifier)
- o This product correct an issue which Firmware reset if there is pending nvm parameter changes

Enhancements

This product enhances to support for LLDP read/write RDE commands.

Supported Devices and Features

This product supports the following network adapters:

- o HPE Ethernet 10Gb 2-port 537SFP+ Adapter
- o HPE Ethernet 10Gb 2-port 537SFP+ FLR Adapter
- o HPE Ethernet 10Gb 2-port 535T Adapter
- o HPE Ethernet 10Gb 2-port 535FLR-T Adapter
- o HPE Ethernet 10/25Gb 2-port 631SFP28 Adapter
- o HPE Ethernet 10/25Gb 2-port 631FLR-SFP28 Adapter

HPE Broadcom NetXtreme-E Online Firmware Upgrade Utility for VMware

Version: 5.17.2 (**Recommended**)

Filename: CP054753.compsig; CP054753.zip

Important Note!

HPE recommends *HPE Broadcom NetXtreme-E Drivers for VMware*, versions 2023.03.00 or later, for use with this firmware.

This software package contains NVM Image version 224.1.102000 with the following firmware versions:

NIC	Bootcode Version	NCSI Version	MBA Version	UEFI Version	CCM Version	RoCE Version
HPE Ethernet 10Gb 2-port 535FLR-T Adapter	224.0.158.0	224.0.158.0	224.0.155.0	224.0.155.0	224.0.155.0	224.0.158.0
HPE Ethernet 10Gb 2-port 535T Adapter						
HPE Ethernet 10/25Gb 2-port 631FLR-SFP28 Adapter						
HPE Ethernet 10/25Gb 2-port 631SFP28 Adapter						
HPE Ethernet 10Gb 2-port 537SFP+ Adapter						
HPE Ethernet 10Gb 2-port 537SFP+ FLR Adapter						

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Fixes

- o This product correct an issue which not allow the user to configure the multi-function mode option with option value string.
- o This product correct an issue which the performance issue is seen with GRO offload (Generic Receive Offload) enable.
- o This product correct an issue which the Firmware upgrade fails if bnxtnm uses the default value. increased the timeout value to sufficient vaule.

Enhancements

- o This product enhances bnxtnm support OTP programming.
- o This product enhances coredump support to dump cache contents.
- o This product enhances Firmware command line module modularity
- o This product enhances to add support for disabling Overflow detection for CQs (Completion Queues) of RoCE (RDMA over converged Ethernet)
- o This product enhances FW support for QUIC key (Quick UDP Internet Connection) context backing store management
- o This product enhances to add support for PCIe TPH (TLP Processing Hints)

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 537SFP+ Adapter
- HPE Ethernet 10Gb 2-port 537SFP+ FLR Adapter
- HPE Ethernet 10Gb 2-port 535T Adapter
- HPE Ethernet 10Gb 2-port 535FLR-T Adapter
- HPE Ethernet 10/25Gb 2-port 631SFP28 Adapter
- HPE Ethernet 10/25Gb 2-port 631FLR-SFP28 Adapter

HPE Broadcom NX1 Online Firmware Upgrade Utility for VMware

Version: 1.33.2 (**Recommended**)

Filename: CP054665.compsig; CP054665.zip

Important Note!

This software package contains combo image v20.24.41 with the following firmware versions:

NIC	Boot Code Version	PXE Version	NCSI Version	UEFI Version	CCM Version
HPE Ethernet 1Gb 2-port 330i Adapter (22BD)	2.10	21.6.2	1.5.42	21.6.43	224.0.155.0
HPE Ethernet 1Gb 4-port 331i Adapter (22BE) HPE Ethernet 1Gb 4-port 331FLR Adapter HPE Ethernet 1Gb 4-port 331T Adapter	1.46	21.6.2	1.5.42	21.6.43	224.0.155.0
HPE Ethernet 1Gb 2-port 332i Adapter (22E8) HPE Ethernet 1Gb 2-port 332T Adapter	1.42	21.6.2	1.5.42	21.6.43	224.0.155.0

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Fixes

This product correct an issue which the Boot Code Version of the Firmware did not get updated after upgrading the Firmware.

Enhancements

- This product enhances the FW Library to support the second NVRAM type.
- This product now supports ESXi8.0

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 1Gb 2-port 330i Adapter (22BD)
- HPE Ethernet 1Gb 4-port 331i Adapter (22BE)
- HPE Ethernet 1Gb 4-port 331FLR Adapter
- HPE Ethernet 1Gb 4-port 331T Adapter
- HPE Ethernet 1Gb 2-port 332i Adapter (22E8)
- HPE Ethernet 1Gb 2-port 332T Adapter

HPE Intel Online Firmware Upgrade Utility for VMware

Version: 3.20.0 (**Recommended**)

Filename: CP051019.compsig; CP051019.zip

Important Note!

This software package contains the following firmware versions for the below listed supported network adapters:

NIC	EEPROM/NVM Version	OROM Version	Single NVM Version
HPE Ethernet 1Gb 2-port 361i Adapter	8000119A	1.3299.0	N/A
HPE Ethernet 1Gb 2-port 361T Adapter	80001147	1.3299.0	N/A
HPE Ethernet 1Gb 2-port 363i Adapter	8000119E	1.3299.0	N/A

HPE Ethernet 1Gb 4-port 366i Communication Board	800011A0	1.3299.0	N/A
HPE Ethernet 1Gb 4-port 366i Adapter	8000119F	1.3299.0	N/A
HPE Ethernet 1Gb 4-port 366FLR Adapter	800011A1	1.3299.0	N/A
HPE Ethernet 1Gb 4-port 366T Adapter	80001146	1.3299.0	N/A
HPE Ethernet 1Gb 2-port 368i Adapter	80003AC5	1.3299.0	N/A
HPE Ethernet 1Gb 2-port 368FLR-MMT Adapter	80003AC5	1.3299.0	N/A
HPE Ethernet 1Gb 4-port 369i Adapter	80003AC3	1.3299.0	N/A
HPE Ethernet 10Gb 2-port 560FLR-SFP+ Adapter	800009E0	1.3299.0	N/A
HPE Ethernet 10Gb 2-port 560SFP+ Adapter	800009E1	1.3299.0	N/A
HPE Ethernet 10Gb 2-port 561T Adapter	80000636	1.3299.0	N/A
HPE Ethernet 10Gb 2-port 561FLR-T Adapter	800005B6	1.3299.0	N/A
HPE Ethernet 10Gb 2-port 568i Adapter	80003AC4	1.3299.0	N/A
HPE Ethernet 10Gb 2-port 568FLR-MMSFP+ Adapter	80003AC5	1.3299.0	N/A
HPE Ethernet 10Gb 2-port 568FLR-MMT Adapter	80003AC5	1.3299.0	N/A
HPE Ethernet 10Gb 2-port 563i Adapter	800035C0	1.1375.0	N/A
HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter	8000D072	1.3299.0	11.1.3
HPE Ethernet 10Gb 2-port 562FLR-T Adapter	800016F1	1.3299.0	10.55.3
HPE Ethernet 10Gb 2-port 562SFP+ Adapter	8000D073	1.3299.0	11.1.3
HPE Ethernet 10Gb 2-port 562T Adapter	800016EF	1.3299.0	10.55.3

The combo image v1.3299.0 includes: Boot Agent: 1GbE - v1.5.89, 10GbE - v2.4.45, 40GbE - v1.1.42 & UEFI Drivers: 1GbE - v9.8.15, 10GbE - v8.1.04, 40GbE - v4.9.38

The combo image v1.1375.0 includes: Boot Agent: 1GbE - v1.5.72, 10GbE - v2.3.46, 40GbE - v1.0.21 & UEFI Drivers: 1GbE - v6.9.13, 10GbE - v5.0.20, 40GbE - v1.5.14

Single NVM Version is new firmware format which represent an unified version in place of the previously used EEPROM/NVM Version or OROM version.

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Fixes

- This product addresses an issue where Option ROM version is missing with some Intel 1GB adapters
- This product addresses an issue where disconnection occurs after rebooting system with HPE Ethernet 1Gb 2-port 368i Adapter and HPE Ethernet 1Gb 4-port 369i Adapter

Supported Devices and Features

This package supports the following network adapters:

- HPE Ethernet 1Gb 2-port 361i Adapter
- HPE Ethernet 1Gb 2-port 361T Adapter
- HPE Ethernet 1Gb 2-port 363i Adapter
- HPE Ethernet 1Gb 2-port 368FLR-MMT Adapter
- HPE Ethernet 1Gb 2-port 368i Adapter
- HPE Ethernet 1Gb 4-port 366FLR Adapter
- HPE Ethernet 1Gb 4-port 366i Adapter
- HPE Ethernet 1Gb 4-port 366i Communication Board
- HPE Ethernet 1Gb 4-port 366T Adapter
- HPE Ethernet 1Gb 4-port 369i Adapter
- HPE Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 560SFP+ Adapter
- HPE Ethernet 10Gb 2-port 561FLR-T Adapter
- HPE Ethernet 10Gb 2-port 561T Adapter
- HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 562FLR-T Adapter

- HPE Ethernet 10Gb 2-port 562SFP+ Adapter
- HPE Ethernet 10Gb 2-port 562T Adapter
- HPE Ethernet 10Gb 2-port 568FLR-MMSFP+ Adapter
- HPE Ethernet 10Gb 2-port 568FLR-MMT Adapter
- HPE Ethernet 10Gb 2-port 568i Adapter

HPE QLogic FastLinQ Firmware Package for Arrowhead adapters

Version: 8.65.01 (**Recommended**)

Filename: ql_hp_ah_mbi_8.65.01_pldm.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- HPE QLogic FastLinQ 10/25/50 GbE Drivers for Linux, version 8.70.6.1-1 or later
- HPE QLogic FastLinQ 10/25/50 GbE Drivers for Microsoft Windows Server x64 Editions, version 8.70.9.0 or later
- HPE QLogic FastLinQ 10/25/50 GbE Multifunction Drivers for VMware, version 5.0.336.0 or later

Fixes

This product addresses an issue where Max Number of Virtual Machine Queues/Physical Function shows zero value in AHS

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 521T Adapter
- HPE Ethernet 10Gb 2-port 524SFP+ Adapter
- HPE Ethernet 10/25Gb 2-port 621SFP28 Adapter
- HPE Ethernet 10/25Gb 2-port 622FLR-SFP28 Adapter
- HPE StoreFabric CN1200R-T Converged Network Adapter
- HPE StoreFabric CN1300R Converged Network Adapter

HPE QLogic FastLinQ Online Firmware Upgrade Utility for VMware

Version: 4.17.0 (**Recommended**)

Filename: CP055122.compsig; CP055122.zip

Important Note!

HPE recommends *HPE QLogic FastLinQ 10/25/50GbE Multifunction Drivers for VMware*, versions 2023.03.00 or later, for use with this firmware.

This software package contains combo image version v8.65.01 includes:

- Boot Code (MFW): 8.65.1.0
- UEFI: 4.1.13.1
- PXE: 2.0.19

The users will only see the combo image versions in the interactive mode firmware update or while using HPSUM/SPP to update the firmware on the supported adapters.

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Fixes

This product addresses an issue where Max Number of Virtual Machine Queues/Physical Function shows zero value in AHS

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 521T Adapter
- HPE Ethernet 10Gb 2-port 524SFP+ Adapter
- HPE Ethernet 10/25Gb 2-port 621SFP28 Adapter
- HPE Ethernet 10/25Gb 2-port 622FLR-SFP28 Converged Network Adapter
- HPE StoreFabric CN1200R-T Converged Network Adapter
- HPE StoreFabric CN1300R Converged Network Adapter

HPE QLogic NX2 Online Firmware Upgrade Utility for VMware
Version: 1.32.0 (**Recommended**)
Filename: CP055125.compsig; CP055125.zip

Important Note!

HPE recommends HPE QLogic NX2 10/20GbE Multifunction Drivers for VMware, versions 2022.09.0 or later, for use with this firmware.

This software package contains combo image v7.19.14 with the following firmware versions:

NIC	Boot Code Version	PXE Version	UEFI Version	iSCSI Version	FCoE Version	CCM Version	L2 Version
HPE Ethernet 10Gb 2-port 530SFP+ Adapter HPE Ethernet 10Gb 2-port 530T Adapter	7.16.13	7.14.13	8.9.3	n/a	n/a	7.14.4	7.12.25
HPE Ethernet 10Gb 2-port 533FLR-T Adapter HPE FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter HPE FlexFabric 10Gb 4-port 536FLR-T Adapter HPE StoreFabric CN1100R Dual Port Converged Network Adapter HPE StoreFabric CN1100R-T Converged Network Adapter	7.16.13	7.14.13	8.9.3	7.14.0	7.14.3	7.14.4	7.12.25

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Enhancements

This product now supports VMware ESXi 8.0

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 530SFP+ Adapter
- HPE Ethernet 10Gb 2-port 530T Adapter
- HPE Ethernet 10Gb 2-port 533FLR-T Adapter
- HPE FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HPE StoreFabric CN1100R Dual Port Converged Network Adapter
- HPE StoreFabric CN1100R-T Converged Network Adapter

Intel Firmware Package For E810-2CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter
Version: 4.10 (**Recommended**)
Filename: HPE_E810_2CQDA2_O_SEC_4p10_PLDMoMCTP_8001518B.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.12.148.0 or later
- Intel ice Drivers for Linux, version 1.10.1.2-1 or later
- Intel icen Driver for VMware, version 2023.03.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Enhancements

- This product now supports RDE Read and Write operations.
- This product now supports Debug Dump feature.
- This product now supports new parameters when software requesting on Port 0(via AQ the connectivity type)

Supported Devices and Features

This product supports the following network adapters:

- Intel E810-2CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter for HPE

Intel Firmware Package For E810-CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter

Version: 4.10 **(Recommended)**

Filename: HPE_E810_CQDA2_4p10_PLDMoMCTP_8001518E.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.12.148.0 or later
- Intel ice Drivers for Linux, version 1.10.1.2-1 or later
- Intel icen Driver for VMware, version 2023.03.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Enhancements

- This product now supports RDE Read and Write operations.
- This product now supports Debug Dump feature.
- This product now supports new parameters when software requesting on Port 0(via AQ the connectivity type)

Supported Devices and Features

This product supports the following network adapters:

- Intel E810-CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter for HPE

Intel Firmware Package For E810-CQDA2 Ethernet 100Gb 2-port QSFP28 OCP3 Adapter

Version: 4.10 **(Recommended)**

Filename: HPE_E810_CQDA2_OCP_4p10_NCSIwPLDMoMCTP_80015190.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.12.148.0 or later
- Intel ice Drivers for Linux, version 1.10.1.2-1 or later
- Intel icen Driver for VMware, version 2023.03.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Enhancements

- This product now supports RDE Read and Write operations.
- This product now supports Debug Dump feature.
- This product now supports new parameters when software requesting on Port 0(via AQ the connectivity type)

Supported Devices and Features

This product supports the following network adapters:

- Intel E810-CQDA2 Ethernet 100Gb 2-port QSFP28 OCP3 Adapter for HPE

Intel Firmware Package For E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 Adapter

Version: 4.10 **(Recommended)**

Filename: HPE_E810_XXVDA2_SD_4p10_PLDMoMCTP_80015188.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.12.148.0 or later
- Intel ice Drivers for Linux, version 1.10.1.2-1 or later
- Intel icen Driver for VMware, version 2023.03.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Enhancements

- This product now supports RDE Read and Write operations.
- This product now supports Debug Dump feature.
- This product now supports new parameters when software requesting on Port 0(via AQ the connectivity type)

Supported Devices and Features

This product supports the following network adapters:

- Intel E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 Adapter for HPE

Intel Firmware Package For E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter

Version: 4.10 **(Recommended)**

Filename: HPE_E810_XXVDA2_SD_OCP_4p10_NCSIwPLDMoMCTP_8001518D.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.12.148.0 or later
- Intel ice Drivers for Linux, version 1.10.1.2-1 or later
- Intel icen Driver for VMware, version 2023.03.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Enhancements

- This product now supports RDE Read and Write operations.
- This product now supports Debug Dump feature.
- This product now supports new parameters when software requesting on Port 0(via AQ the connectivity type)

Supported Devices and Features

This product supports the following network adapters:

- Intel E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE

Intel Firmware Package For E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 Adapter

Version: 4.10 **(Recommended)**

Filename: HPE_E810_XXVDA4_FH_4p10_PLDMoMCTP_8001518F.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.12.148.0 or later
- Intel ice Drivers for Linux, version 1.10.1.2-1 or later
- Intel icen Driver for VMware, version 2023.03.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Enhancements

- This product now supports RDE Read and Write operations.
- This product now supports Debug Dump feature.
- This product now supports new parameters when software requesting on Port 0(via AQ the connectivity type)

Supported Devices and Features

This product supports the following network adapters:

- Intel E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 Adapter for HPE

Intel Firmware Package For E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter

Version: 4.10 **(Recommended)**

Filename: HPE_E810_XXV4_OCP_4p10_NCSIwPLDMoMCTP_8001518A.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.12.148.0 or later
- Intel ice Drivers for Linux, version 1.10.1.2-1 or later
- Intel icen Driver for VMware, version 2023.03.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Enhancements

- This product now supports RDE Read and Write operations.
- This product now supports Debug Dump feature.
- This product now supports new parameters when software requesting on Port 0(via AQ the connectivity type)

Supported Devices and Features

This product supports the following network adapters:

- Intel E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter for HPE

Intel Online Firmware Upgrade Utility for VMware

Version: 3.20.0 **(Recommended)**

Filename: CP055491.compsig; CP055491.zip

Important Note!

This software package contains the following firmware versions for the below listed supported network adapters:

NIC	EEPROM/NVM Version	OROM Version	NVM Version
HPE Ethernet 10Gb 2-port SFP+ OCP3 X710-DA2 Adapter	8000D017	1.3310.0	9.10
HPE Ethernet 10Gb 2-port SFP+ X710-DA2 Adapter	8000D01F	1.3310.0	9.10
Intel I350-T4 Ethernet 1Gb 4-port BASE-T Adapter	80001099	1.3310.0	N/A
Intel I350-T4 Ethernet 1Gb 4-port BASE-T OCP3 Adapter	80001199	1.3310.0	N/A
Intel(R) I350 Gigabit Network Connection (2-port)	8000119C	1.3310.0	N/A
Intel(R) I350 Gigabit Network Connection (4-port)	8000119D	1.3310.0	N/A

The combo image v1.3310.0 includes: Boot Agent: 1GbE - v1.5.89, 10GbE - v2.4.45, 40GbE - v1.1.42 & UEFI Drivers: 1GbE -

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Enhancements

This product enhanced the compatibility with igbn and i40en driver

Supported Devices and Features

This package supports the following network adapters:

- Intel(R) I350 Gigabit Network Connection (2-port)
- Intel(R) I350 Gigabit Network Connection (4-port)
- HPE Ethernet 1Gb 4-port BaseT I350-T4 Adapter
- HPE Ethernet 1Gb 4-port BaseT I350-T4 OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ X710-DA2 OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ X710-DA2 Adapter

Marvell FastLinQ Firmware Package for Arrowhead adapters

Version: 8.65.01 (**Recommended**)

Filename: ql_ah_mbi_open_8.65.01_pldm.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Marvell FastLinQ 10/25/50 GbE Drivers for Microsoft Windows Server x64 Editions, version 8.70.9.0 or later
- HPE QLogic FastLinQ 10/25/50 GbE Drivers for Linux, version 8.70.6.1-1 or later
- HPE QLogic FastLinQ 10/25/50 GbE Multifunction Drivers for VMware, version 5.0.336.0 or later

Fixes

This product addresses an issue where Max Number of Virtual Machine Queues/Physical Function shows zero value in AHS

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10/25Gb 2-port SFP28 QL41232HLCU Adapter
- HPE Ethernet 10/25Gb 2-port SFP28 QL41232HQCU OCP3 Adapter
- HPE Ethernet 10Gb 2-port BaseT QL41132HLRJ Adapter
- HPE Ethernet 10Gb 2-port BaseT QL41132HQRJ OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ QL41132HLCU Adapter
- HPE Ethernet 10Gb 2-port SFP+ QL41132HQCU OCP3 Adapter
- HPE Ethernet 10Gb 4-port SFP+ QL41134HLCU Adapter

Mellanox Firmware Package (FWPKG) - Mellanox MCX631102AS-ADAT Ethernet 10/25Gb 2-port SFP28 Adapter for HPE

Version: 26.35.1012 (**Recommended**)

Filename: 26_35_1012-MCX631102AS-ADA_Ax.pldm.fwpkg

Important Note!

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available

at: <https://docs.nvidia.com/networking/display/ConnectX6LxFirmwarev26351012/Known+Issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30

or higher.

Fixes

The following issues have been fixed in version 26.35.1012:

- The patch to the RDE LLDPEnable property in Port schema would not be updated after the host reboot.
- RDE (Redfish) PATCH operation to LLDPTTransmit properties "ManagementAddressIPv4", "ManagementAddressIPv6" and "ManagementAddressMAC" were applied only in the first attempt, but failed in the next.
- PLDM AEN event receiver media was changed unexpectedly and destination BDF was overridden with garbage when some PLDM packet were received from the SMBus layer.
- PCIe SKP OS generation interval for Gen1 and Gen2.

Enhancements

New Features and Changes in Version 26.35.1012:

- Added support for copy modify header steering action to/from the UDP field.
- Added the following resource dump segments:
 - SEG_HW_STE_FULL that includes dump to STE and all its dependencies
 - SEG_FW_STE_FULL that include dump to FW_STE and to HW_STE_FULL in range
- As the software requires additional space before and after a packet is scattered for its processing for stridden RQ, the hardware will allocate the required room while scattering packets to spare a copy.
- QoS priority trust default state can now be changed using the new nvconfig below:

```
QOS_TRUST_STATE_P1
QOS_TRUST_STATE_P2
The values that can be used to set the default state are:
TRUST_PORT
TRUST_PCP
TRUST_DSCP
TRUST_DSCP_PCP
```

Supported Devices and Features

HPE Part Number	Mellanox Ethernet Only Adapters	PSID
P42044-B21	Mellanox MCX631102AS-ADAT Ethernet 10/25Gb 2-port SFP28 Adapter for HPE	MT_000000575

Mellanox Firmware Package (FWPKG) - Mellanox MCX631432AS-ADAI Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE
Version: 26.35.1012 (**Recommended**)
Filename: 26_35_1012-MCX631432AS-ADA_Ax.pldm.fwpkg

Important Note!

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/ConnectX6LxFirmwarev26351012/Known+Issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 26.35.1012:

- The patch to the RDE LLDPEnable property in Port schema would not be updated after the host reboot.
- RDE (Redfish) PATCH operation to LLDPTTransmit properties "ManagementAddressIPv4", "ManagementAddressIPv6" and "ManagementAddressMAC" were applied only in the first attempt, but failed in the next.
- PLDM AEN event receiver media was changed unexpectedly and destination BDF was overridden with garbage when some PLDM packet were received from the SMBus layer.
- PCIe SKP OS generation interval for Gen1 and Gen2.

Enhancements

New Features and Changes in Version 26.35.1012:

- Added support for copy modify header steering action to/from the UDP field.
- Added the following resource dump segments:
 - SEG_HW_STE_FULL that includes dump to STE and all its dependencies
 - SEG_FW_STE_FULL that include dump to FW_STE and to HW_STE_FULL in range
- As the software requires additional space before and after a packet is scattered for its processing for stridden RQ, the hardware will allocate the required room while scattering packets to spare a copy.
- QoS priority trust default state can now be changed using the new nvconfig below:

QOS_TRUST_STATE_P1
QOS_TRUST_STATE_P2
The values that can be used to set the default state are:
TRUST_PORT
TRUST_PCP
TRUST_DSCP
TRUST_DSCP_PCP

Supported Devices and Features

HPE Part Number	Mellanox Ethernet Only Adapters	PSID
P42041-B21	Mellanox MCX631432AS-ADAI Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE	MT_0000000551

Mellanox Firmware Package (FWPKG) for HPE Ethernet 100Gb 1-port QSFP28 PCIe3 x16 MCX515A-CCAT Adapter : HPE part numbers P31246-B21 and P31246-H21

Version: 16.35.1012 (**Recommended**)

Filename: 16_35_1012-MCX515A-CCA_HPE_Ax.pldm.fwpkg

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available

at: <https://docs.nvidia.com/networking/display/ConnectX5Firmwarev16351012/Known+Issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 16.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 16.35.1012:

- RDE (Redfish) PATCH operation to LLDPTtransmit properties "ManagementAddressIPv4", "ManagementAddressIPv6" and "ManagementAddressMAC" were applied only in the first attempt, but failed in the next.
- PLDM AEN event receiver media was changed unexpectedly and destination BDF was overridden with garbage when some PLDM packet were received from the SMBus layer.
- Bad configuration of number of VFs and SFs led to the consumption of too many functions and triggered a FW assert 0x888E. The reduction flows behavior was fixed to ensure the configuration does not exceed the total number of supported functions.
- InfiniBand L2 QP could not receive RDMA traffic occasionally.
- Running with a debug firmware reduced security as if token was applied.

Enhancements

Important : Security Hardening Enhancements - This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device firmware to this version to improve the firmware security and reliability of your device.

New features and changes included in version 16.35.1012:

- Added support for copy modify header steering action to/from the UDP field.
- Enabled ADP timer to allow the user to configure RC or DC qp_timeout values lower than 16.
- QoS priority trust default state can now be changed using the new nvconfig below:

QOS_TRUST_STATE_P1
QOS_TRUST_STATE_P2

The values that can be used to set the default state are:

TRUST_PORT
TRUST_PCP
TRUST_DSCP
TRUST_DSCP_PCP

Supported Devices and Features

This software package contains the following firmware versions:

Mellanox Ethernet Only Adapters	Firmware Version	PSID
HPE Ethernet 100Gb 1-port QSFP28 PCIe3 x16 MCX515A-CCAT Adapter(P31246-B21 and P31246-H21)	16.35.1012	MT_0000000591

Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 MCX653105A-HDAT Adapter : HPE part numbers P23664-B21 and P23664-H21

Version: 20.35.1012 (**Recommended**)

Filename: 20_35_1012-MCX653105A-HDA_HPE_Ax.pldm.fwpgk

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available

at: <https://docs.nvidia.com/networking/display/ConnectX6Firmwarev20351012/Known+Issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 20.35.1012:

- RDE (Redfish) PATCH operation to LLDPTransmit properties "ManagementAddressIPv4", "ManagementAddressIPv6" and "ManagementAddressMAC" were applied only in the first attempt, but failed in the next.
- The RXT E2E inflight went into an unresponsive state occasionally.
- RDMA partition was reported even if NIC+RDMA mode was disabled.
- PLDM AEN event receiver media was changed unexpectedly and destination BDF was overridden with garbage when some PLDM packet were received from the SMBus layer.

- o An incorrect address issue for XRQ Event Backend Controller Px Syndrome event in multi-host system during FLR.
- o PCIe SKP OS generation interval issue for Gen1 and Gen2.
- o InfiniBand L2 QP could not receive RDMA traffic occasionally.
- o Running with a debug firmware reduced security as if token was applied.
- o PLDM AEN event receiver was required to be cleared on PCIe reset in case the media type was MCTP over PCIe VDM.
- o Asynchronous messages were sent over MTCP before endpoint discovery was done.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 20.35.1012:

- o Added support for copy modify header steering action to/from the UDP field.
- o Enabled ADP timer to allow the user to configure RC or DC qp_timeout values lower than 16.
- o QoS priority trust default state can now be changed using the new nvconfig below:

QOS_TRUST_STATE_P1
QOS_TRUST_STATE_P2

The values that can be used to set the default state are:

TRUST_PORT
TRUST_PCP
TRUST_DSCP
TRUST_DSCP_PCP

- o Added support for using SetEventReceiver PLDM command with mode polling.

Supported Devices and Features

This software package contains the following firmware versions:

Mellanox InfiniBand Adapter	Firmware Version	PSID
HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 MCX653105A-HDAT Adapter (P23664-B21 and P23664-H21)	20.35.1012	MT_0000000451

Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 OCP3 MCX653435A-HDAI Adapter : HPE part numbers P31323-B21 and P31323-H21

Version: 20.35.1012 (**Recommended**)

Filename: 20_35_1012-MCX653435A-HDA_HPE_Ax.pldm.fwpkg

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available

at: <https://docs.nvidia.com/networking/display/ConnectX6Firmwarev20351012/Known+Issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 20.35.1012:

- o RDE (Redfish) PATCH operation to LLDPTransmit properties "ManagementAddressIPv4", "ManagementAddressIPv6" and "ManagementAddressMAC" were applied only in the first attempt, but failed in the next.
- o The RXT E2E inflight went into an unresponsive state occasionally.
- o RDMA partition was reported even if NIC+RDMA mode was disabled.
- o PLDM AEN event receiver media was changed unexpectedly and destination BDF was overridden with garbage when some PLDM packet were received from the SMBus layer.
- o An incorrect address issue for XRQ Event Backend Controller Px Syndrome event in multi-host system during FLR.
- o PCIe SKP OS generation interval issue for Gen1 and Gen2.
- o InfiniBand L2 QP could not receive RDMA traffic occasionally.
- o Running with a debug firmware reduced security as if token was applied.
- o PLDM AEN event receiver was required to be cleared on PCIe reset in case the media type was MCTP over PCIe VDM.
- o Asynchronous messages were sent over MTCP before endpoint discovery was done.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 20.35.1012:

- o Added support for copy modify header steering action to/from the UDP field.
- o Enabled ADP timer to allow the user to configure RC or DC qp_timeout values lower than 16.
- o QoS priority trust default state can now be changed using the new nvconfig below:

```
QOS_TRUST_STATE_P1
QOS_TRUST_STATE_P2
```

The values that can be used to set the default state are:

```
TRUST_PORT
TRUST_PCP
TRUST_DSCP
TRUST_DSCP_PCP
```

- o Added support for using SetEventReceiver PLDM command with mode polling.

Supported Devices and Features

This software package contains the following firmware versions:

Mellanox InfiniBand Adapter	Firmware Version	PSID
HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 OCP3 MCX653435A-HDAI Adapter (P31323-B21 and P31323-H21)	20.35.1012	MT_0000000592

Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 MCX653106A-HDAT Adapter : HPE part numbers P31324-B21 and P31324-H21

Version: 20.35.1012 (**Recommended**)

Filename: 20_35_1012-MCX653106A-HDA_HPE_Ax.pldm.fwpkg

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

ConnectX-6 VPI supports having one port as InfiniBand and the other port as Ethernet according to the following matrix of combinations.

Port #2 - InfiniBand				
Port #1 - Ethernet	HDR/HDR100	EDR	FDR	QDR
200GbE/50GbE	supported	not supported	not supported	supported

100GbE/25GbE	supported	not supported	not supported	supported
40GbE/10GbE	supported	not supported	not supported	supported
1GbE	supported	not supported	not supported	supported

Port #2 - Ethernet				
Port #1 - InfiniBand	200GbE/50GbE	100GbE/25GbE	40GbE/10GbE	1GbE
HDR / HDR100	supported	supported	not supported	supported
EDR	supported	supported	not supported	supported
FDR	not supported	not supported	not supported	not supported
QDR/SDR	supported	supported	not supported	supported

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/ConnectX6Firmwarev20351012/Known+Issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 20.35.1012:

- o RDE (Redfish) PATCH operation to LLDPTransmit properties "ManagementAddressIPv4", "ManagementAddressIPv6" and "ManagementAddressMAC" were applied only in the first attempt, but failed in the next.
- o The RXT E2E inflight went into an unresponsive state occasionally.
- o RDMA partition was reported even if NIC+RDMA mode was disabled.
- o PLDM AEN event receiver media was changed unexpectedly and destination BDF was overridden with garbage when some PLDM packet were received from the SMBus layer.
- o An incorrect address issue for XRQ Event Backend Controller Px Syndrome event in multi-host system during FLR.
- o PCIe SKP OS generation interval issue for Gen1 and Gen2.
- o InfiniBand L2 QP could not receive RDMA traffic occasionally.
- o Running with a debug firmware reduced security as if token was applied.
- o PLDM AEN event receiver was required to be cleared on PCIe reset in case the media type was MCTP over PCIe VDM.
- o Asynchronous messages were sent over MTCP before endpoint discovery was done.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 20.35.1012:

- o Added support for copy modify header steering action to/from the UDP field.
- o Enabled ADP timer to allow the user to configure RC or DC qp_timeout values lower than 16.
- o QoS priority trust default state can now be changed using the new nvconfig below:

```
QOS_TRUST_STATE_P1
QOS_TRUST_STATE_P2
```

The values that can be used to set the default state are:

TRUST_PORT
 TRUST_PCP
 TRUST_DSCP
 TRUST_DSCP_PCP

- o Added support for using SetEventReceiver PLDM command with mode polling.

Supported Devices and Features

This software package contains the following firmware versions:

Mellanox InfiniBand Adapter	Firmware Version	PSID
HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 MCX653106A-HDAT Adapter(P31324-B21 and P31324-H21)	20.35.1012	MT_0000000594

Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 OCP3 MCX653436A-HDAI Adapter : HPE part numbers P31348-B21 and P31348-H21

Version: 20.35.1012 (**Recommended**)

Filename: 20_35_1012-MCX653436A-HDA_HPE_Ax.pldm.fwpgk

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

ConnectX-6 VPI supports having one port as InfiniBand and the other port as Ethernet according to the following matrix of combinations.

Port #2 - InfiniBand				
Port #1 - Ethernet	HDR/HDR100	EDR	FDR	QDR
200GbE/50GbE	supported	not supported	not supported	supported
100GbE/25GbE	supported	not supported	not supported	supported
40GbE/10GbE	supported	not supported	not supported	supported
1GbE	supported	not supported	not supported	supported

Port #2 - Ethernet				
Port #1 - InfiniBand	200GbE/50GbE	100GbE/25GbE	40GbE/10GbE	1GbE
HDR / HDR100	supported	supported	not supported	supported
EDR	supported	supported	not supported	supported
FDR	not supported	not supported	not supported	not supported
QDR/SDR	supported	supported	not supported	supported

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA

software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/ConnectX6Firmwarev20351012/Known+Issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

- The following issues have been fixed in version 20.35.1012:**
- o RDE (Redfish) PATCH operation to LLDPTransmit properties "ManagementAddressIPv4", "ManagementAddressIPv6" and "ManagementAddressMAC" were applied only in the first attempt, but failed in the next.
 - o The RXT E2E inflight went into an unresponsive state occasionally.
 - o RDMA partition was reported even if NIC+RDMA mode was disabled.
 - o PLDM AEN event receiver media was changed unexpectedly and destination BDF was overridden with garbage when some PLDM packet were received from the SMBus layer.
 - o An incorrect address issue for XRQ Event Backend Controller Px Syndrome event in multi-host system during FLR.
 - o PCIe SKP OS generation interval issue for Gen1 and Gen2.
 - o InfiniBand L2 QP could not receive RDMA traffic occasionally.
 - o Running with a debug firmware reduced security as if token was applied.
 - o PLDM AEN event receiver was required to be cleared on PCIe reset in case the media type was MCTP over PCIe VDM.
 - o Asynchronous messages were sent over MTCP before endpoint discovery was done.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 20.35.1012:

- o Added support for copy modify header steering action to/from the UDP field.
- o Enabled ADP timer to allow the user to configure RC or DC qp_timeout values lower than 16.
- o QoS priority trust default state can now be changed using the new nvconfig below:

QOS_TRUST_STATE_P1
QOS_TRUST_STATE_P2

The values that can be used to set the default state are:

TRUST_PORT
TRUST_PCP
TRUST_DSCP
TRUST_DSCP_PCP

- o Added support for using SetEventReceiver PLDM command with mode polling.

Supported Devices and Features

This software package contains the following firmware versions:

Mellanox InfiniBand Adapter	Firmware Version	PSID
HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 OCP3 MCX653436A-HDAI Adapter (P31348-B21 and P31348-H21)	20.35.1012	MT_0000000593

Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR100/Ethernet 100Gb 1-port QSFP56 PCIe4 x16 MCX653105A-ECAT Adapter : HPE part numbers P23665-B21 and P23665-H21
Version: 20.35.1012 (**Recommended**)
Filename: 20_35_1012-MCX653105A-ECA_HPE_Ax.pldm.fwpkg

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/ConnectX6Firmwarev20351012/Known+Issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 20.35.1012:

- o RDE (Redfish) PATCH operation to LLDPTransmit properties "ManagementAddressIPv4", "ManagementAddressIPv6" and "ManagementAddressMAC" were applied only in the first attempt, but failed in the next.
- o The RXT E2E inflight went into an unresponsive state occasionally.
- o RDMA partition was reported even if NIC+RDMA mode was disabled.
- o PLDM AEN event receiver media was changed unexpectedly and destination BDF was overridden with garbage when some PLDM packet were received from the SMBus layer.
- o An incorrect address issue for XRQ Event Backend Controller Px Syndrome event in multi-host system during FLR.
- o PCIe SKP OS generation interval issue for Gen1 and Gen2.
- o InfiniBand L2 QP could not receive RDMA traffic occasionally.
- o Running with a debug firmware reduced security as if token was applied.
- o PLDM AEN event receiver was required to be cleared on PCIe reset in case the media type was MCTP over PCIe VDM.
- o Asynchronous messages were sent over MTCP before endpoint discovery was done.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 20.35.1012:

- o Added support for copy modify header steering action to/from the UDP field.
- o Enabled ADP timer to allow the user to configure RC or DC qp_timeout values lower than 16.
- o QoS priority trust default state can now be changed using the new nvconfig below:

QOS_TRUST_STATE_P1
QOS_TRUST_STATE_P2

The values that can be used to set the default state are:

TRUST_PORT
TRUST_PCP
TRUST_DSCP
TRUST_DSCP_PCP

- o Added support for using SetEventReceiver PLDM command with mode polling.

Supported Devices and Features

This software package contains the following firmware versions:

Mellanox InfiniBand Adapter	Firmware Version	PSID
HPE InfiniBand HDR100/Ethernet 100Gb 1-port QSFP56 PCIe4 x16 MCX653105A-ECAT Adapter (P23665-B21 and P23665-H21)	20.35.1012	MT_0000000452

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

ConnectX-6 VPI supports having one port as InfiniBand and the other port as Ethernet according to the following matrix of combinations.

Port #2 - InfiniBand				
Port #1 - Ethernet	HDR/HDR100	EDR	FDR	QDR
50GbE	supported	not supported	not supported	supported
100GbE/25GbE	supported	not supported	not supported	supported
40GbE/10GbE	supported	not supported	not supported	supported
1GbE	supported	not supported	not supported	supported

Port #2 - Ethernet				
Port #1 - InfiniBand	50GbE	100GbE/25GbE	40GbE/10GbE	1GbE
HDR / HDR100	supported	supported	not supported	supported
EDR	supported	supported	not supported	supported
FDR	not supported	not supported	not supported	not supported
QDR/SDR	supported	supported	not supported	supported

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/ConnectX6Firmwarev20351012/Known+Issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

<p>The following issues have been fixed in version 20.35.1012:</p> <ul style="list-style-type: none"> o RDE (Redfish) PATCH operation to LLDPTransmit properties "ManagementAddressIPv4", "ManagementAddressIPv6" and "ManagementAddressMAC" were applied only in the first attempt, but failed in the next. o The RXT E2E inflight went into an unresponsive state occasionally. o RDMA partition was reported even if NIC+RDMA mode was disabled. o PLDM AEN event receiver media was changed unexpectedly and destination BDF was overridden with garbage when some PLDM packet were received from the SMBus layer. o An incorrect address issue for XRQ Event Backend Controller Px Syndrome event in multi-host system during FLR. o PCIe SKP OS generation interval issue for Gen1 and Gen2.

- o InfiniBand L2 QP could not receive RDMA traffic occasionally.
- o Running with a debug firmware reduced security as if token was applied.
- o PLDM AEN event receiver was required to be cleared on PCIe reset in case the media type was MCTP over PCIe VDM.
- o Asynchronous messages were sent over MTCP before endpoint discovery was done.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 20.35.1012:

- o Added support for copy modify header steering action to/from the UDP field.
- o Enabled ADP timer to allow the user to configure RC or DC qp_timeout values lower than 16.
- o QoS priority trust default state can now be changed using the new nvconfig below:

QOS_TRUST_STATE_P1
QOS_TRUST_STATE_P2

The values that can be used to set the default state are:

TRUST_PORT
TRUST_PCP
TRUST_DSCP
TRUST_DSCP_PCP

- o Added support for using SetEventReceiver PLDM command with mode polling.

Supported Devices and Features

This software package contains the following firmware versions:

Mellanox InfiniBand Adapter	Firmware Version	PSID
HPE InfiniBand HDR100/Ethernet 100Gb 2-port QSFP56 PCIe4 x16 MCX653106A-ECAT Adapter (P23666-B21 and P23666-H21)	20.35.1012	MT_0000000453

Mellanox Firmware Package (FWPKG) for Mellanox MCX623105AS-VDAT Ethernet 200Gb 1-port QSFP56 Adapter for HPE

Version: 22.35.1012 (**Recommended**)

Filename: 22_35_1012-MCX623105AS-VDA_Ax.pldm.fwpkg

Important Note!

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available

at: <https://docs.nvidia.com/networking/display/ConnectX6DxFirmwarev22351012/Known+Issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 22.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 22.35.1012:

- o RDE (Redfish) PATCH operation to LLDPTxmit properties "ManagementAddressIPv4", "ManagementAddressIPv6" and "ManagementAddressMAC" were applied only in the first attempt, but failed in the next.
- o Commands sent by the MLNX_OFED driver to the NIC would fail when loading the VirtIO driver.
- o A firmware limitation caused enabling tx_port_ts to result in syndrome 0x5d2974.
- o PLDM AEN event receiver media was changed unexpectedly and destination BDF was overridden with garbage when some PLDM packet were received from the SMBus layer.
- o PCIe SKP OS generation interval for Gen1 and Gen2.

CPU handling synchronization required separation (run ptp4l with taskset -c [cpu #] prefix) while running heavy traffic.

Enhancements

New features and changes included in version 22.35.1012:

- Improved both TP1a compliance and Physical-layer performance. TX and PLL settings were changed to comply with IEEE 802.3bs TP1a and improved link margins.
- Enabled the firmware to distribute loopback QPs/SQs between all LAG ports during the initial distribution in steering LAG.
- Changed the Tx setting for optics HDR to improve compliance margins.
- HPCC related configurations are now supported via the mlxconfig utility.
- Added support for copy modify header steering action to/from the UDP field.
- Added support for range based lookup. This new capability is available using the following new PRM command:

GENERATE WQE which receives GTA WQE, the command supports "match on range" and num_hash_definer=[1,2] and num_match_ste=[1,2].

For further information, refer to section "RTC Object Format" in the PRM.

- Added support for RoCE based VM migration.
- Added the following resource dump segments:

SEG_HW_STE_FULL that includes dump to STE and all its dependencies

SEG_FW_STE_FULL that include dump to FW_STE and to HW_STE_FULL in range

- As the software requires additional space before and after a packet is scattered for its processing for stridden RQ, the hardware will allocate the required room while scattering packets to spare a copy.
- Improved security offload's Connections per Second (CPS) rate using the general object DEK (PSP TLS etc).
- Added support for pre-copy commands in VF migration flow in order to reduce the migration downtime.
- Optimized performance to support full VF migration flow.
- Increased the VirtIO hardware offload message rate to 20/20 MPPS for 256 virtual devices by optimizing the datapath application code.
- Enabled ADP timer to allow the user to configure RC or DC qp_timeout values lower than 16.
- QoS priority trust default state can now be changed using the new nvconfig below:

QOS_TRUST_STATE_P1

QOS_TRUST_STATE_P2

The values that can be used to set the default state are:

TRUST_PORT

TRUST_PCP

TRUST_DSCP

TRUST_DSCP_PCP

Supported Devices and Features

HPE Part Number	Mellanox Ethernet Only Adapters	PSID
P10180-B21	Mellanox MCX623105AS-VDAT Ethernet 200Gb 1-port QSFP56 Adapter for HPE	MT_0000000435

Mellanox Firmware Package (FWPKG) for Mellanox MCX623106AS-CDAT Ethernet 100Gb 2-port QSFP56 Adapter for HPE

Version: 22.35.1012 (**Recommended**)

Filename: 22_35_1012-MCX623106AS-CDA_Ax.pldm.fwpkg

Important Note!

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available

at: <https://docs.nvidia.com/networking/display/ConnectX6DxFirmwarev22351012/Known+Issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 22.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 22.35.1012:

- o RDE (Redfish) PATCH operation to LLDPTransmit properties "ManagementAddressIPv4", "ManagementAddressIPv6" and "ManagementAddressMAC" were applied only in the first attempt, but failed in the next.
- o Commands sent by the MLNX_OFED driver to the NIC would fail when loading the VirtIO driver.
- o A firmware limitation caused enabling tx_port_ts to result in syndrome 0x5d2974.
- o PLDM AEN event receiver media was changed unexpectedly and destination BDF was overridden with garbage when some PLDM packet were received from the SMBus layer.
- o PCIe SKP OS generation interval for Gen1 and Gen2.
- o CPU handling synchronization required separation (run ptp4l with taskset -c [cpu #] prefix) while running heavy traffic.

Enhancements

New features and changes included in version 22.35.1012:

- o Improved both TP1a compliance and Physical-layer performance. TX and PLL settings were changed to comply with IEEE 802.3bs TP1a and improved link margins.
- o Enabled the firmware to distribute loopback QPs/SQs between all LAG ports during the initial distribution in steering LAG.
- o Changed the Tx setting for optics HDR to improve compliance margins.
- o HPCC related configurations are now supported via the mlxconfig utility.
- o Added support for copy modify header steering action to/from the UDP field.
- o Added support for range based lookup. This new capability is available using the following new PRM command:

GENERATE WQE which receives GTA WQE, the command supports "match on range" and num_hash_definer=[1,2] and num_match_ste=[1,2].

For further information, refer to section "RTC Object Format" in the PRM.

- o Added support for RoCE based VM migration.
- o Added the following resource dump segments:

SEG_HW_STE_FULL that includes dump to STE and all its dependencies

SEG_FW_STE_FULL that include dump to FW_STE and to HW_STE_FULL in range

- o As the software requires additional space before and after a packet is scattered for its processing for stridden RQ, the hardware will allocate the required room while scattering packets to spare a copy.
- o Improved security offload's Connections per Second (CPS) rate using the general object DEK (PSP TLS etc).
- o Added support for pre-copy commands in VF migration flow in order to reduce the migration downtime.
- o Optimized performance to support full VF migration flow.
- o Increased the VirtIO hardware offload message rate to 20/20 MPPS for 256 virtual devices by optimizing the datapath application code.
- o Enabled ADP timer to allow the user to configure RC or DC qp_timeout values lower than 16.
- o QoS priority trust default state can now be changed using the new nvconfig below:

QOS_TRUST_STATE_P1

QOS_TRUST_STATE_P2

The values that can be used to set the default state are:

TRUST_PORT

TRUST_PCP

TRUST_DSCP

TRUST_DSCP_PCP

Supported Devices and Features

HPE Part Number	Mellanox Ethernet Only Adapters	PSID
P25960-B21	Mellanox MCX623106AS-CDAT Ethernet 100Gb 2-port QSFP56 Adapter for HPE	MT_0000000437

Online Firmware Upgrade Utility (ESXi 7.0) for HPE Ethernet 10Gb 2-port 548SFP+ Adapter

Version: 1.0.3 (A) **(Recommended)**

Filename: CP053228.compsig; CP053228.zip

Prerequisites

Use iLO5 firmware version 2.30 or higher with ConnectX4-Lx firmware version 14.32.1010. Thermal sensor reporting on the adapter will not be functional with older versions of iLO5 firmware.

Fixes

The following changes have been made in sub-version 1.0.3(A):

- Product rebuilt to have the new SHA 384 signature.

The following issues have been fixed in version 14.32.1010:

- Firmware got into an unresponsive state and caused unexpected behavior when connecting an optical transceiver that support RxLOS and the remote side port was down.
- The system could not create more than 128K QPs.
- On rare occasions, the system got into an unresponsive state when a peer port went down while using an Optical module.
- Packet Pacing rate was used if asymmetric VFs was enabled.
- Incorrect RNR timeout when trying to set it during the rts2rts_qp transition.
- Issue with RSS on IPSec flows in ConnectX-4 Lx led to performance degradation. In this scenario, the SPI optimization caused packets from a given host to hash to the same CPU core. The fix was to ignore SPI optimization according to l4_type in ConnectX-4 Lx adapter cards.
- The GetInventory NC-SI command reported leading 0xf in firmware version when it started with 0.

Enhancements

Firmware for the following device has been updated to 14.32.1010:

- P11338-B21 (HPE Ethernet 10Gb 2-port 548SFP+ Adapter)

New features and changes included in version 14.32.1010:

- Added 3 new assert filters (Health buffer, NVlog, FW trace). The assert will be exposed now if its severity level is equal to or above the new filter.
- Enabled Rate Limit per VM instead of VM-TC. This capability is implemented by adding support to a new Scheduling element type: rate limit elements that will connect to the rate_limit and will share its rate limit.
- Added support for asymmetrical VFs per PF. To enable it: PF_NUM_OF_VF_VALID must be true, and PF_NUM_OF_VF to a non-zero value.
- Limited the external loopback speed to the used module's capabilities.
- Improved linkup time when using the fast linkup capability.
- Added support for the slow_restart and slow_restart_idle parameters to enable Zero Touch RoCE capability.

Supported Devices and Features

HPE Part Number	Mellanox Ethernet Only Adapters	PSID
P11338-B21	HPE Ethernet 10Gb 2-port 548SFP+ Adapter	HPE0000000038

Online Firmware Upgrade Utility (ESXi 7.0) for HPE Mellanox VPI (Ethernet and Infiniband mode) devices on VMware ESXi 7.0
Version: 1.0.1 (A) (**Recommended**)
Filename: CP053315.compsig; CP053315.zip

Important Note!

Known Issues in firmware 2.42.5000, 2.42.5056, 2.42.5700:

- When using the Quad Small Form-factor Pluggable (QSFP) module RTX320-581, and performing a driver restart for the firmware upgrade/downgrade to take effect, the link does not come up.
Workaround: Reboot the server.
- Enabling/disabling cq_timestamp using mlxconfig is not supported.
- In a card with 2 separate LEDs scheme (a Phy LED and a logic LED) only the Phy LED will lit. Meaning, the orange LED will not be active while the ETH link is in an idle mode.
- In SR-IOV setup, using mlxconfig when the Packet Filter (PF) is passed through to a VM requires a reboot of the Hypervisor.
- Downgrading from v2.30.8000 or later to an earlier version than 2.30.8000 requires server reboot.
Workaround: Reboot the server.
- On ConnectX-3 Ethernet adapter cards, there is a mismatch between the GUID value returned by firmware management tools and that returned by fabric/ driver utilities that read the GUID via device firmware (e.g., using ibstat). Mlxburn/flint return 0xffff as GUID while the utilities return a value derived from the MAC address. For all driver/firmware/software purposes, the latter value should be used.
Workaround: Please use the GUID value returned by the fabric/driver utilities (not 0xffff).
- SBR should be asserted for a minimum of 50 milliseconds for the ConnectX-3 adapters.
- On Pilot1 SL230, PCIe link occasionally does not come up at Gen3 speed.
- RHEL6.3 Inbox driver causes kernel panic when SRIOV is enabled on VPI cards due to driver compatibility issue.
Workaround: Set the "do_ sense=false" parameter in the [IB_TAB] i.
- In advanced steering mode, side band management connectivity may be lost when having more than 8 QP per mcg.

- When SR-IOV is disabled in the system BIOS, a PCI issue is noticed in Ubuntu v12.04.3 with Linux kernel v3.8 which affects NICs of several manufacturers including Mellanox's, preventing them from operating.
Workaround: Enable SR-IOV in the BIOS.
- Mellanox Firmware Tools (MFT) might leave the flash semaphore locked if the tool operation is forced stopped. The locked semaphore prevents the firmware from accessing the flash and causes firmware hang.
Workaround: Clear the semaphore using MFT command: 'flint -clear_semaphore'
- Cable Info MAD reports a wrong cable info when using the MC2210411-SR4 module.
- Gen2 failure at temperature sweep up to 10C/min (for MT27518A1-FDIR-BV only)..
- PCIe Gen2 link unstable at temperature sweep of 10C/min for MT27518A1-FDIR-BV.
- Bloom filter is currently not supported.
- When downgrading from firmware v2.11.0000 and using MFT 3.0.0-3, the following message is displayed due to the mlxconfig tool: You are trying to override configurable FW by non-configurable FW. If you continue, old FW configurations will be cleared, do you want to continue ? (y/n) [n] : y You are trying to restore default configuration, do you want to continue ? (y/n) [n] : y.
- DMFS should not be enabled when working with InfiniBand on MLNX_OFED-2.0.3
- ConnectX®-3 Pro VF device ID is presented the same as ConnectX®-3 VF device ID due to driver limitations.
Workaround: Use the physical function device ID to identify the device.
- Virtual Product Data (VPD) read-only fields are writable.
Workaround: Do not write to read-only fields if you wish to preserve them.
- When working in Virtual Path Identifier (VPI) mode with port1 FDR and port2 40G, error counters misbehave and increase rapidly.
- Setting the device to 128Byte CQ/EQ stride will cause misbehavior of sideband management resulting in communication loss.
- CQ and EQ cannot be configured to different stride sizes.
- Changing port protocol from ETH to IB on port with NCSI/IPMI enabled while the port is connected to ETH switch is not supported.
Workaround: 1. Unplug the cable from the switch 2. Restart driver 3. Change the protocol via the appropriate tools.
- Adapter card MCX349A-XCCN may experience longer linkup times of a few seconds with specific switches.
- Adapter card MCX349A-XCCN does not respond to ethtool "identify" command (ethtool -p/--identify).
- Remote Desktop Protocol (RDP) over IPv6 is currently not functional.
Workaround: Set the default RoCE mode in the software to RoCE v2 (also when not using RoCE)
- Sniffer QP cannot be removed from the regular rule after adding the QP with insertion scheme equals to "push to that rule".
- Since only a single Boot Entry Vector (BEV) per PCI Physical Function is supported, disabling the first port causes the second port to disappear as well.
- The NIC does not notify the driver of a link-down incident when a cable is unplugged from a NIC port with 56GbE port link.
- 56GbE link is not raised when using 100GbE optic cables.
- When working with MLNX_OFED v3.3-1.0.0.0, server reboot could get stuck due to a kernel panic in mlx4_en_get_drvinfo() that is called from asynchronous event handler.
- When running ibdump, loopback traffic is mirroring into the kernel driver.
- MAC address that are set from the OS using ifconfig are not reflected in the OCBB buffer.
- The adapter card cannot raise a 10G link vs. a 40GE capable switch port in C7000 enclosure. It can raise a 1G Link and only if the switch port allows it.
- MTUSB communication via I2C header on primary I2C bus is supported only in live-fish mode.

Fixes

The following changes have been made in sub-version 1.0.1(A):

- Product rebuilt to have the new SHA 384 signature.

Fixes in version 2.42.5000:

- PortRcvPkts counter was prevented from being cleared after resetting it.
- The system Timed Out on the configuration cycle of the Virtual Functions (VFs) when more than 10 Virtual Functions performed FLR and the completion Time Out value was configured to a range of less than 16 msec.
- The server hangs and results in NMI when running "mlxftop -d mt4103_pci_cr0" while restarting the driver in parallel (from a different thread). In this case, the downstream bridge over the device reported completion timeout error.
- In flow_steering, BMC could not receive a ping over IPV6 after running bmc_reboot.
- While closing the HCA, the RX packet caused bad access to resources that did not exist, and consequently caused the QPCGW or the irisc to get stuck.
- The master SMLID and the LID was either 0 or 0xFFFF when the port was neither active nor armed.
- ibdump could not capture all MADs packets.
- link did not go up after reboot.
- Fixed a rare issue that cause the PCIe configuration cycle that arrived during the time of sw_reset to generate 2 completions.
- Network Controller Sideband Interface (NC-SI) did not work when adding the disable_static_steering_ini field in the ini file, due to memory allocation issue for this field in the scratchpad.

Fixes in version 2.42.5056:

- Fixed an issue that resulted in reading from invalid I/O address on handover from UEFI boot to OS boot, when a port was configured as InfiniBand on a VPI adapter device.

Enhancements

Firmware for the following devices are updated to 2.42.5000:

764282-B21
764286-B21

Firmware for the following devices are updated to 2.42.5056:

764283-B21
764284-B21

Firmware for the following device is updated to 2.42.5700:

764285-B21

New features in firmware version 2.42.5000:

- Added support for the following features.
 - new TLV: CX3_GLOBAL_CONF to enable/disable timestamp on incoming packets through mlxconfig configuration.
 - User MAC configuration.
 - Automatically collecting mstdump before driver reset.
 - A mechanism to detect DEAD_IRISC (plastic) from TPT (iron) and raise an assert.
 - A new field is added to "set port" command which notifies the firmware what is the user_mtu size.
- Improved the debug ability for command timeout cases.

New features and changes in firmware version 2.42.5700.

- Modified the mlx_cmd_get_mlx_link_status command return value to return "Link Type = Ethernet" in Ethernet adapter cards.

Supported Devices and Features

Supported Devices:

HPE Part Number	Device Name	PSID
764282-B21	HPE InfiniBand QDR/Ethernet 10Gb 2-port 544+M Adapter	HPE_1350110023
764283-B21	HPE InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+M Adapter	HPE_1360110017
764284-B21	HPE InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+QSFP Adapter	HPE_1370110017
764285-B21	HPE InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+FLR-QSFP Adapter	HPE_1380110017
764286-B21	HPE InfiniBand QDR/Ethernet 10Gb 2-port 544+FLR-QSFP Adapter	HPE_1390110023

Firmware - NVDIMM

[Top](#)

Firmware package for HPE Persistent Memory featuring Intel Optane DC Persistent Memory on HPE Gen10 Plus Servers

Version: 02.02.00.1553 (D) **(Recommended)**

Filename: dcpmm_02.02.00.1553.fwpkg

Important Note!

This software package contains Intel Optane DC Persistent Memory Firmware version 2.2.0.1553

Fixes

This product corrects an issue that three different capacities of Intel Optane DC Persistent Memory are identifiable with three individual device GUID.

Enhancements

- Add ESXi 8.0 support

Supported Devices and Features

This package supports the following Memory Devices:

- HPE 512GB 3200 Persistent Memory Kit featuring Intel Optane DC Persistent Memory
- HPE 256GB 3200 Persistent Memory Kit featuring Intel Optane DC Persistent Memory
- HPE 128GB 3200 Persistent Memory Kit featuring Intel Optane DC Persistent Memory

Firmware package for HPE Persistent Memory featuring Intel Optane DC Persistent Memory on HPE Gen10 Servers

Version: 01.02.00.5446 (C) **(Recommended)**

Filename: dcpmm_01.02.00.5446.fwpkg

Important Note!

This software package contains Intel Optane DC Persistent Memory Firmware version 1.2.0.5446

Enhancements

- Add ESXi 8.0 Support

Supported Devices and Features

This package supports the following Memory Devices:

- HPE 512GB 2666 Persistent Memory Kit featuring Intel Optane DC Persistent Memory
- HPE 256GB 2666 Persistent Memory Kit featuring Intel Optane DC Persistent Memory
- HPE 128GB 2666 Persistent Memory Kit featuring Intel Optane DC Persistent Memory

Firmware - Storage Controller

[Top](#)

Firmware Package - HPE Gen11 Boot Controller NS204i-u, NS204i-d and HPE Gen10 Plus Boot Controller NS204i-p, NS204i-d, NS204i-t, NS204i-r

Version: 1.2.14.1009 (**Recommended**)

Filename: HPE_NS204i_Gen10P_Gen11_1.2.14.1009_A.fwpkg

Important Note!

Current firmware has to be 1.0.14.1063 or later in order to enable PLDM firmware update functionality for the controller. Please find the smart component versions of 1.0.14.1063 in below link:

- Windows: <https://www.hpe.com/global/swpublishing/MTX-be195b2891724ec8bb72c8bb2>
- Linux: <https://www.hpe.com/global/swpublishing/MTX-269e14d0e2524277bf699f433>
- Vmware: <https://www.hpe.com/global/swpublishing/MTX-1ffaca997cf248cd9f832a04c6>

Prerequisites

- iLO 6 version 1.10 or later is required for Gen11 servers.
- iLO 5 version 2.81 or later is required for Gen10/Gen10P servers

Fixes

IML event and Redfish inventory information optimization.

Enhancements

Downstream device FW update through PLDM.

Firmware Package - HPE MR216i-a Gen10 Plus Tri Mode Controller

Version: 52.22.3-4650 (B) (**Recommended**)

Filename: HPE_MR216i-a_Gen10_52.22.3-4650_B.fwpkg

Important Note!

This firmware version to be used on HPE MR216i-a Gen10 Plus Controller.

Enhancements

- Meta data update for Cannery Row Server

Firmware Package - HPE MR216i-p Gen10 Plus Tri Mode Controller with Gen10 and Gen10 Plus servers

Version: 52.22.3-4650 (C) (**Recommended**)

Filename: HPE_MR216i-p_Gen10_52.22.3-4650_C.fwpkg

Important Note!

This firmware version to be used on HPE MR216i-p Gen10 Plus Controller.

Enhancements

- Meta data update for Cannery Row Server
-

Firmware Package - HPE MR416i-a Gen10 Plus Tri Mode Controller
Version: 52.22.3-4650 (B) **(Recommended)**
Filename: HPE_MR416i-a_Gen10_52.22.3-4650_B.fwpkg

Important Note!

This firmware version to be used on HPE MR416i-a Gen10 Plus Controller.

Enhancements

- Meta data update for Cannery Row Server
-

Firmware Package - HPE MR416i-p Gen10 Plus Tri Mode Controller with Gen10 and Gen10 Plus servers
Version: 52.22.3-4650 (C) **(Recommended)**
Filename: HPE_MR416i-p_Gen10_52.22.3-4650_C.fwpkg

Important Note!

This firmware version to be used on HPE MR416i-p Gen10 Plus Controller.

Enhancements

- Meta data update for Cannery Row Server
-

Firmware Package - HPE SR932i-p Gen10 Plus /SR416i-a Gen10 Plus/SR932i-p Gen11/SR416ie-m Gen11 Controllers
Version: 03.01.17.056 (B) **(Recommended)**
Filename: HPE_SR416_SR932_Gen10P_Gen11_03.01.17.056_B.fwpkg

Enhancements

Support ML110 and DL560 Gen11 servers

HPE D3600/D3700/D3610/D3710 12Gb SAS Disk Enclosure ROM Flash Component for VMware (ESXi)
Version: 5.04 (F) **(Recommended)**
Filename: CP054769.compsig; CP054769.md5; CP054769.zip

Important Note!

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted. In single domain configuration, if user hosts an OS in D3000(or any storage box) and flash the SEPs, it will hang/crash everytime as SmartComponent will reset the SEPs after flash/codeload.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D3000.log and flash summary is logged to /var/cpq/Component.log.

Prerequisites

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D3000.log and flash summary is logged to /var/cpq/Component.log.

Fixes

The following fixes were incorporated in this version:

- The Enabled-ClusterS2D command now completes successfully when executed on a SATA drive within a D3610 disk enclosure for a NonStop solution.
- The smart carrier, which is the drive case for SAS drives, now authenticates in the D3610/D3710 drive enclosure.
- Added new 7-segment error codes E0 and E1 to report issues with Fan modules A and B, respectively. These new codes only apply to the D3610/D3710 and only display when running firmware 5.04.
- If the storage enclosure processor within the I/O module fails, a hard reset (power down and then power up) is executed to ensure the processor comes back online.

Please refer to the [Release Notes](#) for the complete listing of fixes, enhancements, known issues and work-arounds corresponding to this firmware.

Enhancements

Added support of ESXi 8.0 U1

Supported Devices and Features

The D3600 / D3700 / D3610 / D3710 Enclosure can be attached to any of the following HPE Storage Controllers and Host Bus Adapters :

- Smart Array P408e-p Controller
- Smart Array E208e-p Controller

HPE D3600B/D3700B/D3610B/D3710B 12Gb SAS Disk Enclosure ROM Flash Component for VMware (ESXi)

Version: 6.00 (**Recommended**)

Filename: CP054910.compsig; CP054910.md5; CP054910.zip

Important Note!

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted. In single domain configuration, if user hosts an OS in D3000B(or any storage box) and flash the SEPs, it will hang/crash everytime as SmartComponent will reset the SEPs after flash/codeload.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D3000B.log and flash summary is logged to /var/cpq/Component.log.

Prerequisites

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D3000B.log and flash summary is logged to /var/cpq/Component.log.

Fixes

The following fixes were incorporated in this version:

- Code optimization to save memory repo.
- TLB exception seen while doing esp reset when expander reset was in progress.
- Added the psoc 8.93 binary in peripheral images, updated the reveille version numbers.
- Added whole new Delta PS-pmbus code , Updated the ESP version number.

Please refer to the [Release Notes](#) for the complete listing of fixes, enhancements, known issues and work-arounds corresponding to this firmware.

Enhancements

Added support of ESXi 8.0 U1

Supported Devices and Features

The D3600B / D3700B / D3610B / D3710B Enclosure can be attached to any of the following HPE Storage Controllers and Host Bus Adapters :

- Smart Array P408e-p Controller
- Smart Array E208e-p Controller

HPE D6020 12Gb SAS Disk Enclosure ROM Flash Component for VMware (ESXi)

Version: 2.74 (M) (**Recommended**)

Filename: CP055783.compsig; CP055783.md5; CP055783.zip

Important Note!

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted. In single domain configuration, if user hosts an OS in D6020(or any storage box) and flash the SEPs, it will hang/crash everytime as SmartComponent will reset the SEPs after flash/codeload.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D6020.log and flash summary is logged to /var/cpq/Component.log.

Prerequisites

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D6020.log and flash summary is logged to /var/cpq/Component.log.

Fixes

The following fixes were incorporated in this version:

- Temperature sensors logic inside gSEP model and SES database
- When an IOM is pulled the surviving IOM reports false critical temperatures

Please refer to the [Release Notes](#) for the complete listing of fixes, enhancements, known issues and work-arounds corresponding to this firmware.

Enhancements

Added support of ESXi 8.0 U1

Supported Devices and Features

The D6020 Enclosure can be attached to any of the following HPE Storage Controllers and Host Bus Adapters :

- Smart Array P408e-p Controller
- Smart Array E208e-p Controller

HPE D8000 12Gb SAS Disk Enclosure ROM Flash Component for VMware (ESXi)

Version: 0130 (A) (**Recommended**)

Filename: CP054772.compsig; CP054772.md5; CP054772.zip

Important Note!

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted. In single domain configuration, if user hosts an OS in D8000(or any storage box) and flash the SEPs, it will hang/crash everytime as SmartComponent will reset the SEPs after flash/codeload.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D8000.log and flash summary is logged to

/var/cpq/Component.log.

Prerequisites

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D8000.log and flash summary is logged to /var/cpq/Component.log.

Fixes

The following fixes were incorporated in this version:

- Smart Array reporting "Storage Enclosure FW upgrade Problem Detected".
- PSU version is showing as "No Ver" after inserted the New bel power PSU.
- GEM_5_2 Coverity defect fix.

Please refer to the [Release Notes](#) for the complete listing of fixes, enhancements, known issues and work-arounds corresponding to this firmware.

Enhancements

Added support of ESXi 8.0 U1

Supported Devices and Features

The D8000 Enclosure can be attached to any of the following HPE Storage Controllers and Host Bus Adapters :

- HPE Smart Array P408e-p Controller
- HPE Smart Array E208e-p Controller

Online Firmware Flash for ESXi - HPE Gen11 Boot Controller NS204i-u, NS204i-d and HPE Gen10 Plus Boot Controller NS204i-p, NS204i-d, NS204i-t, NS204i-r

Version: 1.0.14.1063 **(Recommended)**

Filename: CP056151.compsig; CP056151.zip

Important Note!

VMware **7.0u1** **is** supported by HPE NS204i-p, NS204i-d, NS204i-t and NS204i-r Gen10+ Boot Controller

VMware 7.0 is NOT supported by HPE NS204i-p, NS204i-d, NS204i-t and NS204i-r Gen10+ Boot Controller

Fixes

Fix known issue on v1055 regarding RDE dictionary broken which will cause unexpected FW upgrading error.

Online ROM Flash Component for ESXi (x86) - HPE Smart Array P824i-p MR Gen10

Version: 24.23.0-0048 **(Recommended)**

Filename: CP052319.compsig; CP052319.zip

Fixes

- Fixed an issue that previous configuration may be completely missing at boot. The issue may happen when there is one or more malfunction drive in timeout-recovered loop, and power cycling the system while controller FW initialization.
- Fixed an issue that FW may report Error Code 0x000000d.
- Fixed an issue that Foreign Import from Mutli Span/LD drives with other drives, FW crash and import failure.
- Fixed a FW exception and controller is not detected issue. It may occur during system reboot or FW upgrade in expander environment with multiple drives.
- Fixed an issue that sanitize operation is completed before actual completion from drive.
- Fixed a Machine Check event if drive timeout is triggered when StartStopUnit command is about to finish.

Enhancements

- Change the order of DDF (Disk Data Format) header updates when there are errors existing in DDF headers currently on the drive. This is to avoid potential DDF corruption when there are malfunctioned drives in an array.
- Change spinupdrivecount from 2 to 4 by default. This is to improve the large capacity HDD discovery in system bootup.

Online ROM Flash Component for VMware ESXi - HPE 12Gb/s SAS Expander Firmware for HPE Smart Array Controllers and HPE HBA Controllers

Version: 5.14 (D) **(Recommended)**

Filename: CP056068.compsig; CP056068.zip

Important Note!

- **Do NOT downgrade FW to previous version if your current expander is 5.10; please upgrade to 5.14 immediately.**

Enhancements

Support ESXi8.0

Online ROM Flash Component for VMware ESXi - HPE Apollo 2000 Gen10 Backplane Expander Firmware

Version: 1.00 (F) **(Recommended)**

Filename: CP052254.compsig; CP052254.zip

Enhancements

- Update build environment with SHA384
- Update OS

Online ROM Flash Component for VMware ESXi - HPE Apollo 2000 Gen10 Plus Backplane Expander FW

Version: 1.27 (B) **(Recommended)**

Filename: CP052251.compsig; CP052251.zip

Enhancements

- Update build environment with SHA384
- Update OS

Online ROM Flash Component for VMware ESXi - HPE Apollo 4200 Backplane Expander Firmware

Version: 1.79 (E) **(Recommended)**

Filename: CP054456.zip; CP054456_part1.compsig; CP054456_part2.compsig

Important Note!

- Power cycle / cold reboot is required if firmware is upgraded from version 1.03 or earlier.

Enhancements

Support ESXi8.0

Online ROM Flash Component for VMware ESXi - HPE Apollo 4200 Gen10 Plus Backplane Expander Firmware

Version: 0.39 (C) **(Recommended)**

Filename: CP052260.compsig; CP052260.zip

Prerequisites

- Before upgrading to 0.39(C), please flash to the transition version 0.39 first by standalone update approach to activate the new PID naming.
- 0.39(B) is the minimum version for Gen10plus 4200 expander FW.
- **0.39 transition version link:** <https://www.hpe.com/global/swpublishing/MTX-baec686eb389427aa933bbf9f0>

Enhancements

- Update build environment with SHA384
- Update OS

Online ROM Flash Component for VMware ESXi - HPE Apollo 45xx Gen10 Backplane Expander Firmware

Version: 1.56 (G) **(Recommended)**

Filename: CP052262.compsig; CP052262.zip

Enhancements

- Update build environment with SHA384
- Update OS

Online ROM Flash Component for VMware ESXi - HPE Smart Array P408i-p, P408e-p, P408i-a, E208i-p, E208e-p, E208i-a, P816i-a SR Gen10

Version: 5.32 (B) **(Recommended)**

Filename: CP053855.compsig; CP053855.zip

Fixes

- Fixed an issue where the encrypted data is not accessible for a RAID 50/60 volume when it was failed and healed using "Heal Array".
- Fixed an issue where pointers in PLDM commands were accessed before initialized.
- Fixed an issue where UBM3 backplanes fail to flash.
- Fixed a Predictive Failure drive LED blinking issue.
- Fixed an issue where a re-enabled encrypted single drive RAID 0 logical drive was reported with state Offline after system reboot.
- Fixed long SATA SSD TRIM causing hang.
- Fixed an issue where the product ID of an enclosure was not showing correctly.
- Fixed an issue where the drive bay number for a failed drive is wrong.
- Fixed an issue where the Real Time Clock (RTC) timestamp was not sent to the SES based storage enclosure SEPs attached to internal connectors of the controller.
- Fixed an issue where events are sent continuously if the host does not respond to PlatformEventMessage.
- Fixed an issue where Redfish Volume Create fails when using 4Kn data drives.
- Update Redfish Drive.Identifiers.DurableName to conform to the standard.
- Update Redfish Volume.Identifiers.DurableName to conform to the standard.
- Updated Redfish to the 2021.4 schema bundle.

Enhancements

- Added UBM6 backplane support.
- Added support for SED Local Key Management.
- Added a new HII menu that will attempt to re-enable a previously failed volume whose physical drives are back.
- Added an Unlock Controller option in the HII menu when controller password is set for Controller Based Encryption (CBE).
- Added new HII menu options to configure Controller Based Encryption (CBE).
- Added new HII options to enable and configure SED Local Key Management.
- Added support for the following Redfish ACTION requests:
 - Drive.SecureErase
 - Drive.Reset
 - Storage.ResetToDefaults
- Added support for Redfish PATCH requests for the following properties:
 - Volume.DisplayName
 - Volume.Links.DedicatedSpareDrives
 - Volume.IOPerfModeEnabled
 - Volume.ReadCachePolicy
 - Volume.WriteCachePolicy
 - Drive.LocationIndicatorActive
 - Drive.WriteCacheEnabled

 - StorageController.ControllerRates.ConsistencyCheckRatePercent
 - StorageController.ControllerRates.RebuildRatePercent
 - StorageController.ControllerRates.TransformationRatePercent
- Added the following Redfish alerts:
 - DriveOffline
 - DriveMissing
 - DriveOfflineCleared
 - VolumeOffline
 - VolumeOfflineCleared
 - BatteryMissing
 - BatteryFailure
 - BatteryCharging

 - BatteryOK
 - ControllerDegraded
 - ControllerFailure
 - ControllerPreviousFailure
 - ControllerPasswordRequired
 - ControllerPasswordEntered (changing to ControllerPasswordAccepted in the future)
- Added MaxMembers to Redfish VolumeCollection
- Added 'Reverting' to Redfish Drive.Operations.OperationName used for SED.

- o Added 'NativeDriveEncryption' (SED) to Redfish Volume.EncryptionTypes.
- o Added support for Redfish Drive.EncryptionStatus for SED.
- o Redfish Drive.Status.State will be set to StandbyOffline in the following conditions:
 - SED is Foreign
 - SED is Locked (only for controller owned SEDs)
 - SED is controller owned and controller is waiting on SED adapter password
- o Added support for Redfish Volume.Encrypted for SED.

Firmware - Storage Fibre Channel

[Top](#)

HPE Firmware Flash for Emulex Fibre Channel Host Bus Adapters for VMware vSphere 7.0

Version: 2023.03.01 (**Recommended**)

Filename: CP054526.compsig; CP054526.zip

Important Note!

This Firmware package contains following firmware versions:

Adapter	Speed	Universal Boot Image	Firmware	UEFI	Boot Bios
HPE SN1200E 16Gb Dual Port Fibre Channel Host Bus Adapter	16Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1200E 16Gb Single Port Fibre Channel Host Bus Adapter	16Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1600E 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1600E 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1610E 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1610E 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1700E 64Gb Single Port Fibre Channel Host Bus Adapter	64Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1700E 64Gb Dual Port Fibre Channel Host Bus Adapter	64Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0

Prerequisites

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

Enhancements

This Firmware package contains following firmware versions:

Adapter	Speed	Universal Boot Image	Firmware	UEFI	Boot Bios
HPE SN1200E 16Gb Dual Port Fibre Channel Host Bus Adapter	16Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1200E 16Gb Single Port Fibre Channel Host Bus Adapter	16Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1600E 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1600E 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1610E 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1610E 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1700E 64Gb Single Port Fibre Channel Host Bus Adapter	64Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1700E 64Gb Dual Port Fibre Channel Host Bus Adapter	64Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0

Supported Devices and Features

This component is supported on following Emulex Fibre Channel Host Bus adapters:

16Gb FC Adapter:

- HPE SN1200E 16Gb Dual Port Fibre Channel Host Bus Adapter

- HPE SN1200E 16Gb Single Port Fibre Channel Host Bus Adapter

32Gb FC Adapter:

- HPE SN1600E 32Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1600E 32Gb Single Port Fibre Channel Host Bus Adapter
- HPE SN1610E 32Gb Dual port Fibre Channel Host Bus Adapter
- HPE SN1610E 32Gb Single port Fibre Channel Host Bus Adapter

64Gb FC Adapter:

- HPE SN1700E 64Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1700E 64Gb Single Port Fibre Channel Host Bus Adapter

Software - Management

[Top](#)

HPE Agentless Management Bundle Smart Component on ESXi for Gen10 and Gen10 Plus Servers

Version: 2023.02.01 **(Recommended)**

Filename: cp054509.compsig; cp054509.zip

Fixes

Agentless Management Service

- Removed incorrect reporting of NS204i device in cpqSePCIEDisk MIB.
- Fixed incorrect speed of 100G network adapter reported in cpqNicIfPhysAdapterSpeedMbps OID.
- Fixed missing OS Logical Disk entries in the iLO AHS log.

HPE Fiber Channel and Storage Enablement Bundle Smart Component for ESXi 7.0

Version: 2022.09.01 **(Recommended)**

Filename: cp050934.compsig; cp050934.zip

Enhancements

- Supports VMware ESXi 7.0 U2 and ESXi 7.0 U3

HPE iLO Driver Bundle Smart Component for ESXi 7.0

Version: 2022.09.01 **(Recommended)**

Filename: cp050763.compsig; cp050763.zip

Fixes

- Fixed issue where ilo driver is failing to acquire contiguous physical memory below 4GB causing userworld apps like hponcfg to be unable to communicate with iLO.

Enhancements

- Added support for vSphere 8.0

Smart Storage Administrator (SSA) CLI Smart Component for ESXi 7.0 for Gen10/Gen10 Plus/Gen11 Controllers

Version: 2023.04.01 **(Recommended)**

Filename: cp055515.compsig; cp055515.zip

Enhancements

Support ML110 and DL560 Gen11 servers

Software - Storage Controller

[Top](#)

HPE MegaRAID Storage Administrator StorCLI for VMware7.0 (For Gen10P and Gen11 Controllers)

Version: 2023.04.01 **(Recommended)**

Filename: cp055452.compsig; cp055452.zip

Enhancements

Support HPE ML110 and DL560 Gen11 servers

Software - Storage Fibre Channel

[Top](#)

HPE QLogic Fibre Channel driver component for VMware vSphere 7.0

Version: 2023.03.01 (**Recommended**)

Filename: cp054425.compsig; cp054425.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CPXXXX.xml file.

Prerequisites

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

Enhancements

Driver version 5.3.1.0

Supported Devices and Features

This component is supported on following Qlogic Fibre Channel Host Bus adapters:

16Gb Fibre Channel Host Bus Adapter:

- HPE SN1100Q 16Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HPE SN1100Q 16Gb Single Port PCIe Fibre Channel Host Bus Adapter

32Gb Fibre Channel Host Bus Adapter:

- HPE SN1600Q 32Gb Single Port Fibre Channel Host Bus Adapter
- HPE SN1600Q 32Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1610Q 32Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1610Q 32Gb Single Port Fibre Channel Host Bus Adapter

64Gb Fibre Channel Host Bus Adapter:

- HPE SN1700Q 64Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1700Q 64Gb Single Port Fibre Channel Host Bus Adapter

HPE Storage Emulex Fibre Channel driver component for VMware vSphere 7.0

Version: 2023.03.01 (**Recommended**)

Filename: cp054535.compsig; cp054535.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CPXXXX.xml file.

Prerequisites

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

Enhancements

Updated to Driver version 14.0.543.0

Supported Devices and Features

This component is supported on following Emulex Fibre Channel Host Bus adapters:

16Gb FC Adapter:

- HPE SN1200E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1200E 16Gb Single Port Fibre Channel Host Bus Adapter

32Gb FC Adapter:

- HPE SN1600E 32Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1600E 32Gb Single Port Fibre Channel Host Bus Adapter
- HPE SN1610E 32Gb Dual port Fibre Channel Host Bus Adapter
- HPE SN1610E 32Gb Single port Fibre Channel Host Bus Adapter

64Gb FC Adapter:

- HPE SN1700E 64Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1700E 64Gb Single Port Fibre Channel Host Bus Adapter

Software - System Management

[Top](#)

HPE Agentless Management Bundle for ESXi for HPE Gen10 and Gen10 Plus Servers

Version: 701.11.9.0 (**Recommended**)

Filename: amsdComponent_701.11.9.0.9-1_20793680.zip

Fixes

Agentless Management Service

- Removed incorrect reporting of NS204i device in cpqSePCIEDisk MIB.
- Fixed incorrect speed of 100G network adapter reported in cpqNicIfPhysAdapterSpeedMbps OID.
- Fixed missing OS Logical Disk entries in the iLO AHS log.

HPE Fiber Channel and Storage Enablement Component for ESXi 7.0

Version: 3.9.0 (**Recommended**)

Filename: fc-enablement-component_700.3.9.0.4-1_20266032.zip

Enhancements

- Supports VMware ESXi 7.0 U2 and ESXi 7.0 U3

Smart Storage Administrator (SSA) CLI for VMware 7.0

Version: 6.15.11.0 (**Recommended**)

Filename: ssacli2-component_6.15.11.0-7.0.0_20754029.zip

Enhancements

Initial Build for VMware

Get connected

hpe.com/info/getconnected

Current HPE driver, support, and security alerts delivered directly to your desktop

© Copyright 2022 Hewlett Packard Enterprise Development Company, L.P.

The information contained herein is subject to change without notice. The only warranties for HPE products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HPE shall not be liable for technical or editorial errors or omissions contained herein.

Trademark acknowledgments, if needed.

Updated April 11 2023

